

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 5 February 2021

To : LKK

By Fax: 6256-4315

Attn: Bryan

Tel : 97237799

VEHICLE NO : VCT 3242

Yamaha LC 135

ACCIDENT DATE: 31 January 2021

Description	Qty	Quotation \$
1 Mirror NH	1 set	125.00 X
2 Handle Bar disturb	1	95.00 ✓
3 Steering Cone & Bearing Disturb	1 set	125.00 ✓
4 Brake Lever cut	1	75.00 ✓
5 Balancer NH	1 set	120.00 X
6 Head Lamp Scratched	1	320.00 ✓
7 Front Head Cowling cut	1	250.00 ✓
8 Front Inner Panel cut	1	120.00 X ✓
9 Horn Cover disturb NH	1	90.00 X X
10 Front Inner Bracket Panel NH	1	95.00 X
11 Front Mudguard broken	1	185.00 ✓
12 Fork Tube BT	1 set	480.00 ✓
13 Fork Under Bracket Disturb	1	250.00 ✓
14 Front Rim disturb	1	320.00 ✓
15 Brake Disc NH	1	190.00 X
16 Wheel Axle disturb BT	1	125.00 ✓
17 Front Side Panel L/RH crack cut	2	280.00 ✓
18 Footrest broken N/S rear	1	65.00 ✓
19 Gear Pedal NH	1	75.00 X
20 Rear Side Panel LH NH	1	165.00 X
21 Pillion Grip Bar cut	1	85.00 ✓
22 Rear LH Signal disturb	1	65.00 ✓

tail lamp - \$180.00 mostly broken ✓

Sub-Total

3,700.00

Vibration - \$180.00 cut ✓

Less 10%

370.00

Sub-Total

3,330.00

3170.00

10% 2853.00

Open up the survey for hidden damaged + general 10% 2853.00

Signature: _____ Date: _____

VEHICLE NO : VCT 3242

Yamaha LC 135

Nett items

- | | | |
|---|--|-----------------------------|
| 1 | Towing fee | 40.00 X |
| 2 | Remove & replace necessary parts, align & etc | 250.00 150/- |
| 3 | Remove & replace fork tube, oil seal, fork under bracket, fork rim, brake disc, & re-align back the same | 200.00 80/- |
| 4 | Supply body decal sticker | 120.00 60/- 80/- |
| 5 | Re-align body frame | 280.00 MN |

Sub-Total

890.00

Nett Total

4,220.00

Number plate - 8/5-N 104
HCC ✓

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

05/02/2021 @ 1600hrs

HA Arthur

1/5 hr

5 days

myu

2kk Auto

3178.00

4/5 2,200/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: