

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel: 6844 2475

E-mail: claims@teamworkgarage.com

ROC number: 201015366H REPAIR PERFORMA INVOICE

Vehicle number SMV3034M Make / Model **AUDI R8** Chassis number WUAZZZ4268N004178 Accident date 02.02.21 Reference 2102-09

Qty	Particulars	Reference	2102-09
40,			Unit Price - SGD \$
	PARTS REPLACEMENT - LIST ITE	MS	
1	FRONT BUMPER		
1	FRONT BUMPER LOWER LIP		
2	FRONT BUMPER RETAINER X FRONT BUMPER SPONGE		
1	FRONT BUMPER SPONGE	\checkmark	
1	FRONT BUMPER REINFORCMENT X	QQ	
2	FRONT BUMPER SIDE COVER 1 PC	1/10	
1 1	FRONT GRILLE EMBLEM OFF		
1			
1 1	RADIATOR INC. X		
2	RADIATOR HOUSING X Y		
1	FRONT PDC SENSOR X BONNET \(\bar{1} \)		
	BONNET EMBLEM		
'	BONNET EMBLEM 7. NEC		
		Loss FO	
		Less 5%	
1	1		
	PARTS REPLACEMENT - SPECIAL	NFTT ITFMS	
1 SET	FRONT BUMPER CLIP	NETT TIEMS	
1 SET	FRONT GRILLE CLIP		
1 BOT	COOLANT X NN		
1	NUMBER PLATE CMP		
1	STICKER / ML		600.00
	,,,,,	Subtotal	
	LABOUR AND MISCELLANEOUS C		600.00
		Balance B/F	#REF!
)			
1	CHECK WIRING AND LIGHTNING SYSTEM		60.00 X
2	REMOVE AND TRIMS AND GARNISHES TO FA	ACILITATE REPAIR	150.00 \$ 60
3	REMOVE AND REFIT RADIATOR AND TOP U		200.00
4	PANEL BEATING ON AFFECTED AREAS		1000.00 Saa
5	SPRAY PAINTING ON AFFECTED AREAS		1000.00 400
6	APPLY ANTI RUST ON AFFECTED AREAS		150.00 × 1
		Subtotal	
		Grand total	
			milet :

Spays.

Company After up air plot-s

Company After up air plot-s

Company 11/3/2/