

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	UNITED OVERSEAS INSURANCE LTD		Ref:	CS/UOI21001704/R1td3e2	
	3 ANSON ROAD #. SPRINGLEAF TOV	28-01 VER SINGAPORE 079909	Date:	03/03/2021	
			Code:	UOI2	
1.	Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKM 813Y	
	Policy No.	DHOM120031811701	Coverage (\$)	0.00	
	Claim No.		Excess (\$)	500.00	
	Assign From	JOSEPHINE WONG	Assign Date	04/02/2021	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA 200 (R18 SR)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	WDD1173432N072285	Colour	BLACK	
	Odometer	52302 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	PIRELLI	6 mm	
	L/H Front Tyre	225/40 R18	PIRELLI	6 mm	
	R/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
	L/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	02/02/2021	Inspection Date	15/02/2021	
	Survey held at	CYCLE & CARRIAGE INDUSTRIES PL			
		188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a.	Remarks				
	A)THE MARKET VALUE IS S\$68,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Work	ing Days	