



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKM813Y*

Kamila G Kirpalani

62C Meyer Road
Singapore 437889

Mobile: +6583636066

Vehicle & Document Information

WIP No **48224**
Reg No/Reg Date **SKM813Y* / 23/10/2014**
Date In/Mileage **0**
Chassis No **WDD1173432N072285**
Engine No **27091030346442**
Make/Model **MB/CLA 200 BlueEFFICIENCY (C**
Colour/Trim **021 191 Cosmos Blac/ 041 151-Leather Twi**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00003	Cash	04/02/2021/ 16:20	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : DHOM120031811701 // 02/02/2021
DRIVE IN/EXCESS : 04/02/2021 // \$500
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT

M FRONT BUMPER

M FRONT BUMPER COMPANY SIGN

M FRONT DISTANCE SENSOR

M SPACER RING

M RH/ HEADLAMP COVER

M RH/ HEADLAMP COVER SPRING

M RH/ FRONT FENDER INTERMEDIATE LAYER

M RH/ HEADLAMP

M RH/ HEADLAMP SEALING FRAME

M RH/ HEADLAMP CONTROL UNIT

M RH/ HEADLAMP RANGE ADJUSTMENT

M FRONT CROSS MEMBER

M RH/ FRONT CROSS MEMBER ABSORBER

1.00	1421.95	00.00	1421.95
1.00	63.68	00.00	63.68
2.00	182.48	00.00	364.96
2.00	6.35	00.00	12.70
1.00	70.74	00.00	70.74
1.00	4.93	00.00	4.93
1.00	17.94	00.00	17.94
1.00	2632.90	00.00	2632.90
1.00	75.02	00.00	75.02
1.00	870.27	00.00	870.27
1.00	314.71	00.00	314.71
1.00	340.68	00.00	340.68
1.00	160.37	00.00	160.37

960 1920.00

600 960.00

380.00

120.00

LKK Auto Consultants hence notify
the Repairer of the following:

Confirmed & accepted by:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp
is subject to final approval from Insurance Company

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Nett **9,730.85**
7% GST on **9730.85** **681.16**
Total Payable 10,412.01

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg