



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKM813Y\*

United Overseas Insurance Ltd

United Overseas Insurance Ltd  
Motor Claims Department  
3 Anson Rd #28-01 Springleaf Tow  
Singapore 079909  
Mobile: +6583636066

### Vehicle & Document Information

WIP No **48224**  
Reg No/Reg Date **SKM813Y\* / 23/10/2014**  
Date In/Mileage **16/02/2021/ 52302**  
Chassis No **WDD1173432N072285**  
Engine No **27091030346442**  
Make/Model **MB/CLA 200 BlueEFFICIENCY (C**  
Colour/Trim **021 191 Cosmos Blac/ 041 151-Leather Twi**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSI00003	Cash	18/02/2021/ 14:36	K0	301 / Kerlyn Ong					
					S BPNSUB SUPPLY 1 PC NO PLATE bt X CTR/ BASIC MOUNTING FOR BUMPER cra	1.00	179.22	00.00	179.22

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY


Confirmed & accepted by

7% GST on **Nett 239.22** **16.75**  
**Total Payable 255.97**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg