



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20210203/0465		LOCATION OF FIRE: Along Bukit Timah Expressway (BKE) Towards Woodlands, before Exit 5 Near lamp post no. 213, Singapore	
FIRE REPORTED ON : 03 February 2021			
TIME OF CALL : 13:52:25 hrs			
STATION COVERAGE : Bukit Batok Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: A car (make, model and registration plate number burnt beyond recognition) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using two compressed air foam backpacks and a 38mm hose line jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the car was damaged. The nearby plants at the road shoulder and a section of the vehicular impact guardrail sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY: MUHAMMAD FAIZAL BIN MAZLAN for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.