

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 08 Feb 2021

Preliminary Advice

Vehicle No	: SJJ8886L	Accident Date	: 03/02/2021
Make	: BMW 116I	Policy No.	: PNPV2020-00010255
Assignment Date	: 05/02/2021	Excess	: S\$0.00
Date of Inspection	: 05/02/2021	Est. Duration of Repair	: 0
Inspection At	: AH LIM MOTOR COMPANY (SIN MING) 176 SIN MING DRIVE #05-12, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	35,169.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,831.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :