

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3092D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	BENT	1,258.30	1,258.30
1	ROCKER PANEL GARNISH LH	TO REPAIR SEE LABOUR	576.00	-
1	REAR BUMPER CTR GUARD	NOT NECESSARY	552.60	-
	LESS 25% DISCOUNT		-596.73	-314.58
			1,790.17	943.72
<u>NETT ITEMS</u>				
1	FRT DOOR COMFORTDELGRO LH (N)	NECESSARY	75.00	75.00
1	REAR DOOR APPS LH (N)	CUT	80.00	80.00
1	REAR FENDER (PETROL ONLY) (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-18.50	-18.50
			166.50	166.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			50.00	-
<u>LABOUR</u>				
	PANEL BEATING - REAR FENDER LH ETC. INCLUSIVE THE REPAIR OF ROCKER PANEL GARNISH LH.		800.00	700.00
	SPRAY PAINT - REAR BUMPER ETC.		1,200.00	1,000.00
	TUFF COAT ON AFFECTED PARTS.		60.00	30.00
	R/I REVERSE SENSOR.		120.00	30.00
			2,180.00	1,760.00
GRAND TOTAL			4,186.67	2,870.22
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,870.22

Report Ref No. NS/INC21001725/T1tf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.