

YM7604Y.

TP AXA.

Nissan MKB37.

Ceilia.

MKB37BN00117

Front Number Plate	Bent	30(SN) ✓
Front Bumper	Distorted. ^{MR}	2085 ✓
Front Bumper Lower Cross Member.		595 X
Front Bumper Bracket x 02.	Bent	248 x 2 = 496 ✓
Front Bumper Signal Lamp x 02	und	288 x 2 = 576 ✓
Front Bumper Lamp x 02	und	204 x 2 = 408 ✓
Front Bumper Lamp Outer Garnish x 02.	Missing	215 x 2 = 430 ✓
Front Bumper Side Reflector (Orange)	^{MR} RH 38 X 860	860 x 2 = 1720 ✓
Headlamp x 02	RH could	295 x 2 = 590 ✓
Headlamp Base Panel x 02	RH shield	265 x 2 = 530 ✓
Front Side Lamp x 02	RH could	58 x 2 = 116 ✓
Front Reflector x 02	RH missing	689 ✓
Front Grille	could	189 ✓
Front Grille Logo	MR	50(SN) ✓
Front Grille Clips.	MR	442
Front Corner Panel x 02.	RH Buckled	442 x 2 = 884 ✓
Wiper Panel Garnish.	Red	664. ✓
Wiper Panel ^{Garnish} Hinge x 02	Bent	118 x 2 = 236 ✓
Wiper Panel Garnish Handle.	Red	241 ✓

YM7604Y.

Front Panel.	Dented	1850. ✓
Front Panel Lock.	Dup	87 ✓
"Sing Mah" Sticker	} MR	300(SN). ^{180(SN)}
"Nissan Diesel" Sticker		65 ✓
Wiper Arm x 02.	RH crushed	155 x 2 = 310. ¹⁸⁵
Front Windscreen Moulding	} MR	385 X
Front Windscreen Sealant.		100(SN) X
Front RH Step Panel.	Distorted	298. ✓
Front RH Step Board (Aluminium).	Dup	279 ✓
Front RH Door	Buckled	5350 ✓
Front RH Door Hinge x 02	Best	290 x 2 = 580 ✓
Front RH Door Check.	Dup	268. ✓
Front RH Door Reflector	lit	221 ✓
Front RH Door Weatherstripe.	MR	342 X
Front RH Door Lock.	Dup	319. ✓
Front RH Door Pillar (Outer).	Distorted	1595 ✓

YM7604Y.

- Front RH Door Inner Trim Board ² ~~892~~ X
Front RH Door Inner Trim Board Clips ^{per} 50(SN) ✓
Front RH Door Advertisement Sticker ^{new} ~~400(SN)~~ 200(SN) ✓
Front RH Wheel Arc Panel ^{disturbed} 548. ✓
Front RH Wheel Arc Panel Outer Garish ^{disturbed} 489. ✓
Front RH Wheel Arc Panel outer Garish Moulding ^{missing} 341 ✓
Front RH Wheel Arc Panel Cowling ^{disturbed} 342 ✓
Front RH Wheel Arc Panel Cowling Clips ^{per} 50(SN) ✓
Front RH Door Rear Panel ^{Buckled} 955 ✓
Front RH Door Rear Panel Glass Moulding ^{new} 145 ✓
Front RH Door Rear Panel Glass Sealant ^{new} 80(SN) ✓
Front RH Door Rear Panel ^{new} 180(SN) ✓
Front RH Door Rear Panel Advertisement Sticker ^{new} 300(SN) ✓
Front RH Wheel Rim ² ~~450(SN)~~ X
Front RH Wheel Rim Cover ^{per} 180(SN) X
Front RH Tyre. ^{lit} ~~380(SN)~~ 250(SN) ✓

YM 76044.

Rees Number Plate. ^{NEM} 30(SN) X

Rees Aluminium Tailgate. ^{Ryis} 8000(SN);

Rees Aluminium Tailgate Bar Hinge. ^{Ryis} 1000(SN). X

Rees Aluminium Tailgate Hydraulic Outer x02 ^{NEM} 3500XL = 700(SN) X

Rees Aluminium Tailgate Hydraulic Bracket Outer x02 ^{NEM} 300X2 = 600(SN) X
LH Bent 1500(SN)

Rees Aluminium Tailgate Hydraulic Inner x02 ^{NEM} 2500X2 = 5000(SN) X

Rees Aluminium Tailgate Roller x02 ^{NEM} 100X2 = 200(SN). X

Rees Chassis Cross Member ^{NEM} 857 X

Rees Chassis Cross Member ^{RH and} 95 X2 = 190. X

Tail Lamp x02. ^{NEM} 325XL = 650. X

Rees Wooden Chassis Member (Longitudinal) x02 ^{LH and} 800(SN) X
1200X2 = 2400(SN)

Rees Under Rider ^{Ryis} 1100(SN) X

Rees Under Rider Side x02. ^{Ryis} 480XL = 960(SN) X

60km/h Sticker. }
10 Pax Sticker. } ^{Per}

10(SN) ✓

10(SN) ✓

YM7604Y.

Peer Wooden Deck Front Partition Panel.	new	1800(SN).
Side Wooden Gate RH.	Dryd	2500(SN).
Side Wooden Gate Hinge x 02	th	180x2=360(SN)
Side Wooden Gate Lock Latch (Front)	best	165(SN) ✓
Side Wooden Gate Metal Frame.		
Front Cabin Peer Air Cleaner Duct.		258. ✓
Front Cabin Peer Air Cleaner Box	th	540 ✓
Side Wooden Gate Lower Guard.	m	600(SN) ✓
Air Can Condenses.	Dishd	525 ✓
Engine Mounting x 02.	torn	295x2=590 ✓
Engine oil	m	250(SN) ✓
Engine Block Gasket.	m	400(SN) ✓
Alternator	Dryd	1880. ✓
Alternator Bracket.	th	65(SN) ✓

YM7604Y.

Panel Beating and to remove front cabin.	2800 2400
Spray Painting.	2000 1500.
Wiring.	200 100.
To remove front windscreen.	380 X
To remove dashboard.	450 X
To remove upholstery	300 200
To transfer front door fittings.	200 120.
To remove front door rear panel glass.	250 120.
To remove condenser and to top up air con gas.	180 100.
To remove engine block and to repair and overhaul engine block.	1000 580.
To remove rear wooden deck to facilitate repairs.	600 1000.
To straighten rear chassis members.	1800 800
To remove rear aluminium platform and hydraulic pumps.	800 500.
To varnish wooden side gate.	380 120.
Tooling Fees.	250 150.

hist: 24911.

Am 10%: 22419.90

S. N: 5255

Labour: 7290

total: 34964.90

1/s 18K.

32 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: