

DETAILS

SUPPLEMENTARY

nce

ce: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2021)  
 M1-MPV TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)  
 Repairer's (Price-denominated Standard List)

a: (Unsubmitted, no print-code for SFJ9988S)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

fo: Items/values not in reference catalogue are prefixed with an asterisk \*

tes on Parts

Part No.	Particulars	%Disc	%Depr	Amount
	*WASHER CONTAINER	0.00	0.00	<i>Red</i> *65.00 F —
	*COND TUBE	0.00	0.00	<i>Ry</i> *165.00 F —
	*RADIATOR SHROUD	0.00	0.00	<i>0.1</i> *100.00 F —
	*R/F AIR DUCT	0.00	0.00	<i>CK</i> *40.00 F —
	*RAD S/SEAL LOWER	0.00	0.00	<i>Red</i> *40.00 F —
	*RAD S/SEAL LOWER LH	0.00	0.00	<i>Red</i> *40.00 F —
	*BONNET STOPPER	0.00	0.00	<i>M/S</i> *10.00 F —
	*AIR FUEL SENSOR	0.00	0.00	<i>Ry</i> *180.00 F —
	*R/F S-MEMBER REINF	0.00	0.00	<i>Ry</i> *80.00 F —
	<b>Total Parts (S\$)</b>			<b>720.00</b>

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS