

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: MSIG	DATE	: 5/2/2021
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT			
VEHICLE DETAILS			
VEHICLE NO	: SMK8272S		
VEHICLE MODEL	: HONDA FREED		
CHASSIS NO	: GB51091058		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAVIER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Del</i>	1	\$ 753.30	\$ 753.30
2	REAR BUMPER SIDE HOLDER <i>re</i>	2	\$ 32.40	\$ 64.80
3	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 90.00	\$ 180.00
4	REAR END PANEL <i>Dented</i>	1	\$ 509.40	\$ 509.40
5	REAR END PANEL TOP GARNISH <i>Del</i>	1	\$ 208.00	\$ 208.00
6	REAR END PANEL TOP GARNISH <i>Inner. Dented</i>	1	\$ 326.20	\$ 326.20
7	TAILLAMP <i>RH Gilded</i>	2	\$ 661.00	\$ 1,322.00
8	TAILGATE <i>Dented</i>	1	\$ 1,115.90	\$ 1,115.90
9	TAILGATE LOCK <i>Del</i>	1	\$ 185.90	\$ 185.90
10	TAILGATE WEATHERSTRIPE <i>lt</i>	1	\$ 241.70	\$ 241.70
11	TAILGATE OUTER CHROME MOULDING <i>new</i>	1	\$ 315.80	\$ 315.80
12	TAILGATE INNER TRIM BOARD <i>Gilded</i>	1	\$ 288.90	\$ 288.90
13	TAILGATE REFLECTOR <i>RH Gilded</i>	2	\$ 368.20	\$ 736.40
14	TAILGATE INNER PULL POCKET <i>Del</i>	1	\$ 55.10	\$ 55.10
15	TAILGATE GLASS MOULDING <i>re</i>	1	\$ 85.90	\$ 85.90
16	HONDA LOGO <i>new</i>	1	\$ 38.40	\$ 38.40
17	FREED EMBLEM <i>new</i>	1	\$ 56.90	\$ 56.90
18	FLOOR PANEL <i>Repr</i>	1	\$ 1,578.00	\$ 1,578.00
19	FLOOR PANEL TOP MAT <i>new</i>	1	\$ 588.20	\$ 588.20
20	REAR FENDER INNER TRIM BOARD <i>Gilded</i>	2	\$ 424.10	\$ 848.20
21	REAR EXHAUST PIPE <i>new</i>	1	\$ 971.10	\$ 971.10
22	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 28.50	\$ 28.50

23 Rear Bumper Inner
Garnish. LH.

46.80
turn

558546
468368

TOTAL PRICE: \$ 10,498.60
LESS 25% 20% \$ 2,250.72
SUB TOTAL PRICE: \$ 8,247.88

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 <i>30</i>
4	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00 <i>✓</i>
5	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00 <i>✓</i>
6	REVERSE SENSOR <i>new</i>	1 SET	\$ 280.00	\$ 280.00 <i>20</i>
8	TAILGATE OUTER CHROME MOULDING CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00 <i>x</i>
9	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 <i>30</i>
10	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00 <i>✓</i>
11	REAR FENDER INNER TRIM BOARD CLIPS <i>new</i>	2 SETS	\$ 30.00	\$ 60.00 <i>✓</i>
			TOTAL :	\$ 600.00

460

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	1100	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	1100	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE VIDEO RECORDER	\$ 100.00	50	
8	TO REMOVE UPHOLSTERY	\$ 150.00	100	
9	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	80	
10	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
11	TO REMOVE EXHAUST PIPE	\$ 150.00	X	

TOTAL: \$ 4,130.00

2740

ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,847.88

TOTAL LABOUR COST: \$ 4,130.00

TOTAL REPAIR COST: \$ 12,977.88

total: 7883.68

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

4/si 6.3k
07 Days

6.3k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: