

HH MOTOR TRADING

①

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054.
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934
Co Reg No. 53122819C

Vehicle No : GBK 6TB	Accident Date : 3.2.2021
Mileage :	Make / Model : TOYOTA Dyna
	CHASSIS : JTFAT35Y30K210171
Date :	Fax NO. : 6445 2934

(Front)

Items			
1	Front Bumper	589.50 de✓	727.10
2	Front Bumper clip (set)	na✓	38.00
3	Front RAD Grill	387.72 na✓	573.15
4	Front RAD Grill clip	na✓	38.00
5	Front headlamp LH	350 na✓?	1,145.80
6	Front headlamp RH	350 na✓?	1,145.80
7	Front RAD Grill Lower Grash	one pc } NSP	
8	Front RAD Grill Top Grash		
9	Front RAD Grill Logo (TOYOTA)	na✓	95.35
10	Front Panel	530 bt✓	1,144.35
11	Front Panel Logo (Dyna)	na✓	74.10
12	Front NO. Plate	35 bt✓	50.00
13	Front Panel clip	na✓	38.00
14	Front wiper panel	262.50 dt✓	416.15
15	Front wiper panel clip	na✓	30.00
16	Front wiper ARM LH & RH @ 106.15x ^{mm}	na✓	332.00
17	Front wiper link & motor	na✓	727.15
18	Front wiper nozzle 2pc @ 65.30x2 ^{mm}	na✓	130.60
19	Front windscreen moulding	na✓	110.10
20	Front Corner panel LH & RH @ 258.15x ^{mm}	na✓	516.30
21	Front LH Side mirror Bracket	bt✓	269.15
			13191.42
			25%
			2393.55

HH MOTOR TRADING

(1A)

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934 H.P. 8131 6098
Co Reg. No. 53122819C

GBK 67 B Front Labour

To straighten, remove & replace damaged parts, Bumper, cut & weld Front panel straighten of Chassis frame 800 \$1400

To respray painting on affected area 800.
(Bumper, Rad Grill, corner panel, Front panel, inner panel & effect area) \$1500

To remove and reinstall Front cab Door Box, trim, Board, handle & necessary photo. ? 180Xmm \$400.

To remove and reinstall Air-con blower, Cooling Coil, pipe & Air-con Gas 120 \$180.

To remove and fix Front windscreen for repair ✓ \$120

To check electrical wiring system 30. \$80

To spray anti-rust coating on effect area 30. \$120

Est to repair 7 days. 1900

HH MOTOR TRADING

(5)

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934
Co Reg No. 53122819C

Vehicle No: GBR 67B	Accident Date: 3.2.2021
Mileage:	Make / Model: Toyota Dyna
	CHASSIS: JTFAT35Y30K201177
Date:	Fax NO.: 6445 2934

(Rear)

Items

1	Tail lamp RH / LH @ 240.15 x 2	ad✓	\$480.30
2	Tail Lamp Bracket RH / LH @ 166.95 x 2	bt✓	\$333.90
3	Rear Chassis frame and cross member	R✓	\$950.00
4	Rear number plate Bracket	100 bt✓	\$155.10
5	Number plate Lamp	x	\$69.10
6	Rear Spare Tyre Bracket.	x	\$69.00
7	Exhaust tail pipe & Box	x	\$410.15
8	Exhaust Rubber 2 pc @ 45.10 x 2	x	\$90.20
9	Rear Spare Tyre mount.	x	\$258.10
10			\$27.50

25% - 620.62.

Special nett items.

Rear Reverse Sessler

200 nm✓ \$280.00

9004 → Rear Cabin Door Frame & Lock handle (LH) ✓ \$1250.00

9005 → Rear Cabin Door Frame & Lock handle (RH) bt✓ \$1250.00

Rear Cabin floor panel Beam R✓ \$1000.00

Rear Cabin Door Frame Lock holder x 2 .6t✓ \$180.00

Rear Cabin Door Hinge x 2 LH @ 60 R✓ \$120.00

Rear Cabin Door Hinge x 2 RH @ 60 R✓ \$120.00

Rear No. Plate with Casing 40 bt✓ \$50.00

TO km strecker ne✓ \$15.00

300 → Rear Cabin Door Frame LH strecker & Lock ad✓ \$480

300 → Rear Cabin Door Frame RH strecker & Lock ad✓ \$480

2635

HH MOTOR TRADING

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934 H/F: 8151 6989
Co. Reg. No. 53122819C

DA

HBK 67B Rear

Labour to remove and replace damage park
including strengthening and reposition
replacement parts. (Tune bracket, mount) 200
\$ 600.

To remove and replace damage rear Cabin
14/PM Door frame, floor panel, Beam 700
and realign rear cargo cabin \$ 1200

To slippy paint and to carry on
Cabin Door, chassis frame, & floor panel 450.
\$ 600

To check wiring for proper function 30.
& remove & fix up rear door \$ 120

To carry out anti-rust treatment 30
\$ 60

1510

Est to repair 7 days. 2393.56

1900

Tanpin 17415717

620.62

wp 10/2/21 @ 10am

2635

L/S Resign after repair

1510

10 days

9059.16

Tanpin e / Mantu.com

L/S \$ 7250.

10 days