

HH MOTOR TRADING

①

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054.
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934
Co Reg No. 53122819C

Vehicle No: GBK 6TB | Accident Date: 3.2.2021
Mileage: | Make / Model: TOYOTA Dyna
Date: | CHASSIS: JTFAT35Y30K210171
Fax NO.: 6445 2934

(Front)

Items			
1	Front Bumper	589.50 de✓	727.10
2	Front Bumper clip (set)	na✓	38.00
3	Front RAD Grill	387.72 cm✓	573.15
4	Front RAD Grill clip	na✓	32.00
5	Front headlamp LH	450 cm✓?	1,145.80
6	Front headlamp RH	450 cm✓?	1,145.80
7	Front RAD Grill Lower Granch	one pc }	NSP
8	Front RAD Grill Top Granch		
9	Front RAD Grill logo (TOYOTA)	na✓	95.35
10	Front Panel	630 bt✓	1,144.35
11	Front Panel Logo (Dyna)	na✓	74.10
12	Front NO. plate	35 bt✓	50.00
13	Front Panel clip	na✓	38.00
14	Front wiper panel	262.50 d✓	416.15
15	Front wiper panel clip	na✓	30.00
16	Front wiper ARM LH & RH @ 106.12x ^{mm}	na✓	332.00
17	Front wiper link & motor	na✓	727.15
18	Front wiper nozzle 2pc @ 65.30x ^{mm}	na✓	130.60
19	Front windscreen moulding	na✓	110.10
20	Front Corner panel LH & RH @ 258.15x ^{mm}	na✓	516.30
21	Front LH side mirror bracket	bt✓	269.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

25%

3491.42
2618.55

HH MOTOR TRADING

(1A)

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934 H/F: 2131 6999
Co. Reg. No. 53122819C

GBK 67 B Front Labour

To straighten, remove & replace damaged parts, Bumper, cut & weld Front panel straighten of Chassis frame	800 \$1400
To respray painting on affected area (Bumper, RAD Grill, corner panel, Front panel, inner panel & effect area)	800 \$1500
To remove and reinstall Front cab Door Box, trim, Board, hinge & necessary	photo? 180Xmm \$400.
To remove and reinstall Air-con blower Cooling Coil, pipe & Air-con Gas	120 \$180.
To remove and fix Front underbody for repair	✓ \$120
To check electrical wiring system	30. \$80
To spray anti-rust coating on effect area	30 \$120
Est to repair T days.	1900

HH MOTOR TRADING

(5)

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054.
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934
Co Reg No. 53122819C

Vehicle No: GBK 67B	Accident Date: 3.2.2021
Mileage:	Make / Model: Toyota Dyna
	CHASSIS: JTFAT35BOK50177
Date:	Fax No.: 6445 2934

(Rear)

Items		
1 Tail Lamp RH / LH @ 40.15 x 2	ant ✓	\$480.30
2 Tail Lamp Bracket RH / LH @ 166.95 x 2	bt ✓	\$333.90
3 Rear Chassis Frame and cross member	Rt ✓	\$950.00
4 Rear number Plate Bracket	100 bt ✓	\$155.10
5 Number Plate Lamp	x	\$69.10
6 Rear Spare Tyre Bracket	x	\$269.00
7 Exhaust tail pipe & Box	nn x	\$410.15
8 Exhaust Rubber 2 pc @ 45.10 x 2	x	\$90.20
9 Rear Spare Tyre mount	x	\$258.10
10		914.20
	25% -	685.65

Special nett items

8000 → Rear Reverse Sensor	200 nm ✓	\$280.00
8000 → Rear Cabin Door Frame & Lock handle (LH)	bt ✓	\$1250.00
8000 → Rear Cabin Door Frame & Lock handle (RH)	bt ✓	\$1250.00
Rear Cabin floor panel Beam	Rt ✓	\$1000.00
Rear Cabin Door Frame Lock holder x 2	.6t ✓	\$180.00
Rear Cabin Door Hinge x 2 LH @ 60	Rt ✓	\$120.00
Rear Cabin Door Hinge x 2 RH @ 60	Rt ✓	\$120.00
Rear No. Plate with Casting	40 bt ✓	\$50.00
TO km stretcher	rec ✓	\$15.00
300 → Rear Cabin Door Frame LH stretcher & Logo	ant ✓	\$480
300 → Rear Cabin Door Frame RH stretcher & Logo	ant ✓	\$480
		2635

HH MOTOR TRADING

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934 H/F 2131 6988
Co. Reg. No. 53122819C

2A

BBK 67B Rear

Labour to remove and replace damage parts
including strengthening and reposition
replacement parts. (Tyne bracket, mount) 300.
\$ 600.

To remove and replace damage rear cabin 700
LH/RH Door frame, floor panel, Beam \$ 1200
and realign rear cargo cabin

To slippy paint and to rekey on 450.
cabin door, chassis frame, & floor panel \$ 600

To check wiring for proper function 30.
& remove & fix up rear border \$ 120

To carry out anti-rust treatment 30.
\$ 60

1510

Est to repair 7 days. 2618.56

Tanpin 17415717

wp 10/2/21 @ 10am

L/S Repairing after repair 2635

10 days 1510

Tanpin e / Mento.com 9349.21

L/S \$ 7500.

10 days