

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Wednesday, 9 June 2021 2:29 pm
To: Shiau Chan (LKKAUTO)
Subject: RE: SMO-TP GBK 67B SURVEYED BY TAUFIKH

Dear Shiau Chan,

AUDIT CHECK DONE FOR GBK67B, FOUND REPAIRER REMARK OF NO. OF DAYS FOR REPAIR IS 7 DAYS, IS LESS THAN OUR SURVEYOR RECOMMENDATION 10 DAYS.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 9 June, 2021 1:37 PM
To: Simon Ho (LKKAUTO)
Subject: RE: SMO-TP GBK 67B SURVEYED BY TAUFIKH

Dear Simon,

For your re-audit before Taufikh finalise with repairer.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Sent: Friday, 28 May 2021 10:37 am
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: SMO-TP GBK 67B SURVEYED BY TAUFIKH

Dear Shiau Chan,

AUDIT CHECK DONE FOR GBK67B, FOUND SOME PARTS PRICES NEED VERIFICATION

AND SURVEYOR MARKING NEED TO REVIEW.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto)

Sent: Friday, 28 May, 2021 9:33 AM

To: Simon Ho (LKKAuto)

Subject: SMO-TP GBK 67B SURVEYED BY TAUFIKH

Dear Simon,

For your audit before Taufikh finalise with repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)