

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0115/2021/GW 17-Feb-21 CHANG 1 of 1 SMK 1878 R AUDI A3 SB 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	REPAIR SET FOR STEERING BOX <i>nee ✓</i>	\$ 46.00	
GRAND TOTAL		\$ 46.00	

Rasmu
26/02/21

For Premium Automobiles Pte Ltd




Authorised Signature

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Adnan

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1878 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT SIDE MEMBER TRIM-RH <i>Dented</i>		\$ 2,293.00	✓
2 FRONT FENDER -RH <i>Dented</i>		\$ 851.00	✓
3 FRONT FENDER POP RIVET <i>new</i>	8	\$ 27.00	✓
4 FRONT FENDER ATTACHMENT PARTS-RH <i>new</i>		\$ 72.00	✗
5 FRONT FENDER BRACE-RH <i>?</i>		\$ 96.00	?
6 FRONT FENDER BRACKET-RH <i>?</i>		\$ 48.00	?
7 FRONT FENDER CLOSING ELEMENT-RH <i>?</i>		\$ 62.00	?
8 FRONT WHEEL HOUSING LINER-RH <i>Scrap</i>		\$ 169.00	✗ ?
9 FRONT WHEEL HOUSING LINER ATTACHMENT PARTS -RH <i>new</i>		\$ 57.00	?
10 FRONT DOOR-RH <i>Distorted</i>		\$ 2,767.00	✓
11 FRONT DOOR OUTER SEAL-RH <i>new</i>		\$ 161.00	✓
12 BONDING AGENT <i>?</i>		\$ 49.00	?
13 CLEANING SOLUTION <i>?</i>		\$ 68.00	?
14 APPLICATOR <i>?</i>		\$ 8.00	?
15 FRONT DOOR ATTACHMENT PARTS-RH <i>new</i>		\$ 241.00	✗
16 FRONT DOOR CATCH-RH <i>?</i>		\$ 105.00	?
17 FRONT DOOR HINGE HALF UPPER PART-RH <i>?</i>		\$ 44.00	✓
18 UPPER FRONT DOOR HINGE HALF LOWER PART-RH <i>?</i>		\$ 48.00	?
19 UPPER FRONT DOOR HINGE HALF UPPER PART-RH <i>?</i>		\$ 47.00	?
20 LOWER FRONT DOOR HINGE HALF LOWER PART-RH <i>?</i>		\$ 48.00	?
SUB - TOTAL SPARE PARTS		\$ 7,261.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1878 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
41	FRONT ASSEMBLY CARRIER <i>bt</i>	\$	1,000.00	?
42	1 SET OF BONDED RUBBER BUSHES <i>re</i>	\$	112.00	?
43	FRONT LOWER ARM-RH <i>bt</i>	\$	373.00	?
44	FRONT WHEEL BEARING-RH <i>re (Chausky)</i>	\$	579.00	?
45	FRONT WHEEL HUB WITH BEARING-RH <i>bt</i>	\$	478.00	?
46	FRONT GUIDE JOINT-RH <i>bt</i>	\$	124.00	?
47	FRONT COUPLING ROD-RH	\$	98.00	?
48	FRONT STABILIZER BAR	\$	395.00	?
49	FRONT GAS SHOCK ABSORBER <i>bt</i>	\$	259.00	?
50	FRONT DRIVE SHAFT-RH <i>re</i>	\$	958.00	x
51	FRONT STEERING GEAR	\$	4,964.00	?
52	FRONT TRACK ROD-RH <i>bt</i>	\$	92.00	?
53	FRONT TIE ROD END-RH <i>bt</i>	\$	122.00	?
54	FRONT NOISE INSULATION	\$	290.00	?
55	UNDERBODY TRIM-RH <i>Not re</i>	\$	170.00	x
56	REAR B-PILLAR TRIM (BLACK GLOSSY)-RH <i>re</i>	\$	117.00	x
57	REAR WINDOW SLOT SEAL-RH <i>Not re</i>	\$	270.00	x
58	STONE CHIP	S/N	\$ 180.00	✓
59	ACYLIC SEALANT <i>re</i>	S/N	\$ 180.00	✓
60	CAVITY WAX	S/N	\$ 140.00	✓

SUB - TOTAL SPARE PARTS

:


\$ 10,901.00

Paul
26/02/21


SMK 1878 R
17.2.21 13:25

2013- (MQB - 8V) : Standard Suspension (2UA) + (G01 G02 G03 G04 G05 G14 G15 G16 G21 G22 G23 G24 G41 G42 G43 G44 G51) : without Independent Rear Suspension


Left Front




Before Measurements




Right Front



Left Rear



Right Rear



Rear



One or more values are not within specification. Tire wear, handling and safety problems may result.