

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0115/2021/GW
DATE : 4-Feb-21
WIP :

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMK 1878 R

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS ZHANG NING
ADDRESS : BLK 93 B, TELOK BLANGAH
STREET 31#09-183
SINGAPORE 102093
TELEPHONE : HP +65 83998160
TYPE OF CLAIM : OWN POLICY CLAIMS
POLICY NO : 1900081017
VEHICLE NO : **SMK 1878 R**
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 29/03/2019
ENGINE NO : CHZC27360
CHASSIS NO : WAUZZZ8V3KA056588
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Feb-21
PLACE OF ACCIDENT : CARPARK AT CHANGI EAST PROJECT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 1878 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND REINSTALL FRONT SEAT ASSY, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$ 1,800.00	✓
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	280 ✓
4	TO INSTALL SOLAR FILM FOR RHS FRONT WINDOW GLASS.	S/N \$ 400.00	✓ ✓
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	✓
6	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. TO CUT OUT AND WELD RHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	3250 2750 ✓
SUB - TOTAL LABOUR CHARGES		: \$ 10,130.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 1878 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	X ✓ TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS REAR DOOR, RHS WING MIRROR COVER, RHS SILL PANEL AND DOOR ENTRANCES.	\$ 5,050.00 ²⁰⁷⁵	550X3 = 1650 Mirror = 150 Door Entrance : 275 2075
8	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓✓
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓✓
TOTAL LABOUR CHARGES		: <u>\$ 15,892.00</u>	



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1878 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT SIDE MEMBER TRIM-RH <i>dent</i>		\$ 2,293.00	✓ 1834.40
2 FRONT FENDER -RH <i>dent</i>		\$ 851.00	✓ 680.40
3 FRONT FENDER POP RIVET <i>new</i>	8	\$ 27.00	✓ 21.12
4 FRONT FENDER ATTACHMENT PARTS-RH <i>new</i>		\$ 72.00	✓
5 FRONT FENDER BRACE-RH <i>blue new</i>		\$ 96.00	? X
6 FRONT FENDER BRACKET-RH <i>blue new</i>		\$ 48.00	? X
7 FRONT FENDER CLOSING ELEMENT-RH <i>blue new</i>		\$ 62.00	? X
8 FRONT WHEEL HOUSING LINER-RH <i>new</i>		\$ 169.00	✓ 134.80
9 FRONT WHEEL HOUSING LINER ATTACHMENT PARTS -RH <i>new</i>		\$ 57.00	? X
10 FRONT DOOR-RH <i>Distorted</i>		\$ 2,767.00	✓ 2213.60
11 FRONT DOOR OUTER SEAL-RH <i>new</i>		\$ 161.00	✓ 128.40
12 BONDING AGENT		\$ 49.00	? X
13 CLEANING SOLUTION		\$ 68.00	? X
14 APPLICATOR		\$ 8.00	? X
15 FRONT DOOR ATTACHMENT PARTS-RH <i>new</i>		\$ 241.00	✓
16 FRONT DOOR CATCH-RH <i>blue new</i>		\$ 105.00	? X
17 FRONT DOOR HINGE HALF UPPER PART-RH		\$ 44.00	? X
18 FRONT DOOR HINGE HALF LOWER PART-RH		\$ 48.00	? X
19 FRONT DOOR HINGE HALF UPPER PART-RH		\$ 47.00	? X
20 FRONT DOOR HINGE HALF LOWER PART-RH		\$ 48.00	? X
UPPER /LOWER			
SUB - TOTAL SPARE PARTS		\$ 7,261.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1878 R

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT DOOR HANDLED EXTERIOR-RH <i>Dishe d</i>	\$	374.00	<i>298.80</i>
22	FRONT DOOR HANDLE CAP-RH <i>Missing</i>	\$	54.00	<i>42.48</i>
23	FRONT DOOR SLIDE VALVE-RH <i>Damaged</i>	\$	22.00	<i>17.28</i>
24	FRONT DOOR HANDLE SENSOR-RH <i>Dmd</i>	\$	228.00	<i>182.40</i>
25	FRONT DOOR UNDERLAY-RH REAR <i>Dmd</i>	\$	6.00	<i>4.64</i>
26	FRONT DOOR UNDERLAY-RH FRONT <i>Dmd</i>	\$	5.00	<i>3.92</i>
27	FRONT DOOR LOCK CYLINDER-RH <i>3 Damged</i>	\$	504.00	<i>403.80</i>
28	FRONT DOOR MOUNTING BAR-RH <i>↓</i>	\$	161.00	<i>128.80</i>
29	FRONT DOOR BOWDEN CABLE <i>Not Nec</i>	\$	52.00	<i>X</i>
30	FRONT MIRROR EXTERIOR MOUNTING-RH <i>Dishe d</i>	\$	1,024.00	<i>819.20</i>
31	FRONT MIRROR CAP-RH <i>Missing</i>	\$	169.00	<i>135.20</i>
32	FRONT MIRROR GLASS-RH <i>crackd</i>	\$	1,687.00	<i>1349.60</i>
33	FRONT WINDOW REGULATOR MOTOR-RH <i>Not Nec</i>	\$	268.00	<i>X</i>
34	FRONT CORNER TRIM-RH <i>Not Nec</i>	\$	46.00	<i>+</i>
35	FRONT WINDOW GUIDE-RH <i>Not Nec</i>	\$	420.00	<i>+</i>
36	FRONT B-PILLAR (BLACK GLOSSY) TRIM-RH <i>Not Nec</i>	\$	105.00	<i>+</i>
37	FRONT WINDOW SLOT SEAL-RH <i>Not Nec</i>	\$	270.00	<i>215.60</i>
38	FRONT ROOF MOLDING-RH <i>Not Nec</i>	\$	591.00	<i>+</i>
39	FRONT DOOR WINDOW-RH <i>Not Nec</i>	\$	231.00	<i>181.40</i>
40	FRONT ALUMINIUM RIM-RH <i>Not Nec</i>	\$	1,166.00	<i>932.80</i>
SUB - TOTAL SPARE PARTS			\$ 7,383.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1878 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 FRONT ASSEMBLY CARRIER <i>Bent</i>	\$	1,000.00	? <i>800</i>
42 1 SET OF BONDED RUBBER BUSHES <i>for tear</i>	\$	112.00	? <i>89.00</i>
43 FRONT LOWER ARM-RH <i>Bent</i>	\$	373.00	? <i>298</i>
44 FRONT WHEEL BEARING-RH <i>new</i>	\$	579.00	? <i>462.80</i>
45 FRONT WHEEL HUB WITH BEARING-RH <i>Damaged</i>	\$	478.00	? <i>382.40</i>
46 FRONT GUIDE JOINT-RH <i>new</i>	\$	124.00	? <i>98.80</i>
47 FRONT COUPLING ROD-RH <i>Not Nec.</i>	\$	98.00	? <i>X</i>
48 FRONT STABILIZER BAR	\$	395.00	? <i>X</i>
49 FRONT GAS SHOCK ABSORBER <i>Damaged.</i>	\$	259.00	? <i>206.80</i>
50 FRONT DRIVE SHAFT-RH <i>new</i>	\$	958.00	<i>X</i>
51 FRONT STEERING GEAR <i>Not Nec.</i>	\$	4,964.00	? <i>X</i>
52 FRONT TRACK ROD-RH <i>Bent</i>	\$	92.00	? <i>73.04</i>
53 FRONT TIE ROD END-RH <i>Bent</i>	\$	122.00	? <i>97.00</i>
54 FRONT NOISE INSULATION <i>Not nec</i>	\$	290.00	? <i>X</i>
55 UNDERBODY TRIM-RH <i>Not nec</i>	\$	170.00	<i>X</i>
56 REAR B-PILLAR TRIM (BLACK GLOSSY)-RH <i>new</i>	\$	117.00	<i>X</i>
57 REAR WINDOW SLOT SEAL-RH <i>Not nec</i>	\$	270.00	<i>X</i>
58 STONE CHIP <i>2</i>	S/N	\$ 180.00	✓ <i>180</i>
59 ACYLIC SEALANT <i>2</i>	S/N	\$ 180.00	✓ <i>180</i>
60 CAVITY WAX	S/N	\$ 140.00	✓ <i>140</i>
SUB - TOTAL SPARE PARTS	:	\$	<u>10,901.00</u>

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1878 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 METAL FILLER POWDER <i>Nec</i>	S/N	\$ 280.00	✓ 280
62 SUNDRIES <i>Nec .</i>		\$ 400.00	? 244.80
TOTAL SPARE PARTS	:	\$ 26,225.00	
TOTAL LABOUR CHARGES	:	\$ 15,892.00	
GRAND TOTAL	:	\$ 42,117.00	42,163

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian King
05/02/21

Not Authorised, 13 Days
15 Days. S/S

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0115/2021/GW
17-Feb-21
CHANG
1 of 1
SMK 1878 R
AUDI A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REPAIR SET FOR STEERING BOX <i>nee ✓</i>	\$ 46.00	36.16
GRAND TOTAL		\$ 46.00	

For Premium Automobiles Pte Ltd

R. Asu
26/02/21



Authorised Signature