

REPAIR ESTIMATE\*

VEHICLE NO SHD7240S

DATE 18.02.21

MAKE :

CHIANG/NTUC

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER		fn -	\$1,052.20
1	RADIATUR GRILLE		X nn	\$1,480.00
1	BONNET SEAL		fn ✓	\$31.90
10	BUMPER CLIP		nn ✓	\$22.00
1	FRONT BUMPER BRACKET TOP LH/		X S X	\$44.80
1	FRONT BUMPER BRACKET SIDE /LH		nn X	\$28.60
1	HEAD LAMP LH		X	\$1,800.00
1	LH WING MIRROR		bno ✓	\$670.00
1	FRONT BUMPER BRACKET SIDE /LH		de ✓	\$49.20
	<b>SUB TOTAL</b>		1825.30	<b>\$5,178.70</b>
	<b>20.00%</b>		1460.24	<b>\$1,035.74</b>
				<b>\$4,142.96</b>
1	FRT COMFORT LOGO STICKER		nn ✓	\$75.00
1	REAR DOOR COMFORT APP STICKER		nn ✓	\$80.00
1	FRONT FENDER ADVERTISEMENT		nn ✓	\$100.00
1	FRONT DOOR ADVERTISEMENT		nn ✓	\$100.00
1	REAR DOOR ADVERTISEMENT		nn ✓	\$100.00
1	REAR FENDER ADVERTISEMENT		nn ✓	\$100.00
			555	<b>\$555.00</b>
	<b>Labour Charge</b>			
	Panel Beating		560	\$750.00
	Spray painting		750	\$1,000.00
	tuff coat		nn X	\$120.00
	Check lighting		30	\$50.00
	<b>TOTAL LABOUR</b>		1340	<b>\$1,920.00</b>
	<b>ESTIMATE TOTAL</b>		3355.24	<b>\$6,617.96</b>
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tamper 97415744  
 'wp' 4/2/21 10:4pm  
 1/3 Resurvey after repair  
 3 days.  
 Tamper 1/1/21 10:4pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature