



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2201580

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 21/03/2022
Reference CC6/CTI21001755/Dea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 3524U
Insured Veh. GBA 6399G
Claim No. SNM21D200736/C02
Policy No. DMCVSNA00049062000
Accident Date 04/02/2021
Inspection Date 05/02/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21001755/Dea3q2 Date: 21/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 6399G	Veh. Inspected	SHD 3524U	
Policy No.	DMCVSNA00049062000	Coverage (\$)	0.00	
Claim No.	SNM21D200736/C02	Excess (\$)	0.00	
Assign From		Assign Date	05/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU503529702	Colour	BLUE	
Odometer	742761 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/02/2021	Inspection Date	05/02/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3524U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	BENT / DENTED	499.90	499.90
1	FRONT BUMPER LOWER REINFORCEMENT BRACKET	NOT NECESSARY	330.00	-
1	FRONT SIDE MEMBER REINFORCEMENT PANEL (LH)	NOT NECESSARY	320.70	-
1	FRONT SIDE MEMBER SIDE COVER	NOT NECESSARY	172.50	-
1	LAMP ASSY ,FOG ,LH	MTG BROKEN	920.00	920.00
1	FRONT BUMPER SIDE RETAINER	SERVICEABLE	77.00	-
1	FRONT LOWER SIDE RAIL (LH)	NOT NECESSARY	230.80	-
1	COVER ,FRONT BUMPER HOLE ,LH	NOT NECESSARY	28.38	-
1	ABSORBER ,FRONT BUMPER ,LOWER	NOT NECESSARY	127.70	-
1	UNIT ASSY ,HEADLAMP ,LH (LED)	CRACKED	3,455.00	2,637.60
1	HEADLAMP ECU	NOT NECESSARY	682.60	-
1	HEAD LAMP PANEL (LH)	NOT NECESSARY	240.10	-
1	TOP PANEL CENTRE	NOT NECESSARY	364.98	-
1	TOP PANEL SIDE	NOT NECESSARY	145.90	-
1	FENDER SUB-ASSY ,FRONT LH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD	DEFORMED / TORN	38.00	38.00
1	FRONT FENDER SHIELD CLIP	NECESSARY	14.90	14.90
1	FRONT FENDER HYBRID EMBLEM ,LH	NECESSARY	86.50	86.50
1	BRACKET ,FRONT SIDE PANEL ,LH	NOT NECESSARY	86.30	-
1	PANEL SUB-ASSY ,FRONT DOOR ,LH	TO REPAIR SEE LABOUR	1,264.00	-
1	FRONT DOOR HINGE UPPER	NOT NECESSARY	91.20	-
1	FRONT DOOR HINGE LOWER	NOT NECESSARY	91.20	-
1	FRONT DOOR CHECK	NOT NECESSARY	153.52	-
1	FRONT DOOR TRIMBOARD	NOT NECESSARY	725.00	-
1	FRONT DOOR WEATHER STRIP	NOT NECESSARY	457.90	-
1	MIRROR ASSY ,OUTER REAR VIEW ,LH	NOT NECESSARY	1,728.70	-
1	FRONT WHEEL RIM	CUT	1,570.55	1,570.55
1	FRONT WHEEL RIM CAP	NOT FITTED	189.60	-
1	FRONT WHEEL HUB CAP	NOT FITTED	177.70	-
1	FRONT WHEEL HUB BEARING	DAMAGED	560.10	560.10

Report Ref No. CC6/CTI21001755/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT LOWER ARM (LH)	DISTORTED	637.50	637.50
1	FRONT SHOCK ABOSBRER (LH)	DISTORTED	401.80	401.80
1	ABSORBER TOP MOUNTING	NOT NECESSARY	196.20	-
1	FRONT DRIVE SHAFT (LH)	NOT NECESSARY	1,764.00	-
1	RACK & PINION ASSY	NOT NECESSARY	1,634.90	-
1	BAR ,STABILIZER	NOT NECESSARY	360.00	-
1	LINK ASSY ,FRONT STABILIZER ,LH	NOT NECESSARY	199.00	-
1	KNUCKLE ,STEERING ,LH	DISTORTED	580.80	580.80
1	JOINT ASSY ,LOWER ,BALL ,FRONT (LH)	DISTORTED	199.98	199.98
1	END SUB-ASSY ,TIE ROD ,LH	DISTORTED	159.30	159.30
1	SENSOR ,SPEED ,FRONT LH	NOT NECESSARY	446.50	-
	LESS 20% DISCOUNT		-4,471.20	-
	LESS 25% DISCOUNT		-	-2,313.06
			17,884.81	6,939.17
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER LOGO (SN)	NOT NECESSARY	87.10	-
1	FRONT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (LH) (50%) (SN)	CUT / PUNCTURE	216.00	108.00
			378.10	183.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY ,FRONT DOOR ,LH .		1,600.00	700.00
	SPRAY PAINTING CHARGE		1,400.00	600.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT .	NOT NECESSARY	80.00	-
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	150.00
	RE-SET FRT ABS SYSTEM.	NOT NECESSARY	200.00	-
	REMOVE/REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-

Report Ref No. CC6/CTI21001755/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			5,170.00	1,730.00
GRAND TOTAL			23,432.91	8,852.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,900.00

Report Ref No. CC6/CTI21001755/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3524U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3524U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3524U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

