

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 04-Feb-20

Address : MR TEO AH KOW
BLK 412A FERNVALE LINK
#09-23
SINGAPORE 791412

Reference : TP 1272/02/21
Vehicle No : SJW 5489B
Make/Model : TOYOTA ALTIS
Insurance Co. : NTUC

RE : QUOTATION TO SJW 5489B FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>		<u>QTY</u>	<u>AMT \$</u>	
1)	FRONT BUMPER <i>de</i>	1	\$	581.70
2)	FRONT BUMPER RETAINER RH <i>ne</i>	1	\$	144.30
3)	FRONT FENDER RH <i>lt</i>	1	\$	712.90
4)	FRONT FENDER COWLING RH <i>? X svc</i>	1	\$	199.85
5)	HEADLAMP RH <i>scr</i>	1	\$	608.80
6)	TYRE RIM <i>scr</i>	1	\$	596.50 300 S/N
7)	BUMPER/ FENDER CLIPS <i>ne</i>	10	\$	55.00
8)	BONNET <i>repair X</i>	1	\$	1,041.50
LIST PRICE TOTAL			\$	3,940.55
LESS DISCOUNT 25%			\$	985.14
LIST PRICE TOTAL AFTER LESS			\$	2,955.41
NETT PRICE TOTAL				\$0.00
TOTAL PARTS COST				<div style="border: 1px solid black; padding: 2px;">\$2,955.41</div>

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND PANEL BEAT & ALIGN.	\$	800.00 400 (4 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER & BONNET AND OTHER AFFECTED AREA.	\$	600.00 / (3 PANELS)
3)	TO CHECK & RECTIFY WIRING AND FOCUS HEADLAMP	\$	80.00 30
4)	TO REPLACE TYRE RIM AND BALANCING.	\$	50.00 /

5) TO COMPUTER WHEEL ALIGNMENT

\$ ~~80.00~~ 60

LABOUR TOTAL

\$ 1,610.00

TOTAL ESTIMATED REPAIR COST

\$ 4,565.41

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair

Hp 90010068

5 days

4/5

08/02/2021 @ 1110

Repy after repair