

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Tan Kwong Luck Robert
	Reg No/Reg Date SMC7198Y / 19/07/201
	Date In/Mileage / 31234
	Chassis No KNAFJ411MJ5762532
	Engine No G4FGHH692768
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/02/2021/ 17:08	BLE	261 / Edwin Caina	28632
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000					800 1600.00
RENEW FR ¹ BUMPER & LH WINGMIRROR					
REPAIR LHF DOOR & LHR DOOR					1400.00
E PNT98000					
RESpray FR ¹ BUMPER, LHF, FENDER, LHF, DOOR & LHR DOOR					30.00
M SUNDRY					
RENEW LHF TYRE & WHEEL BALANCE					260.00
M SUNDRY					
SUPPLY LHF TYRE-KUMHO-TN					30.00
A 54900099					
CHECK WIRING ELECTRICAL SYSTEM					120.00
A 10028901					
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					120.00
A WHEELALIGNMENTBP					
To Conduct Computerize Full Wheel Alignment					40 80.00
M SUNDRY					
APPLY ANTI CORROSION ON AFFECTED AREAS					20.00
M SUNDRY					
Sundries					
M COVER-FR BUMPER X R					1.00 633.00 20.00 506.40
M BRACKET-FR BUMPER SIDE MTG, LH 1 X MM					1.00 13.00 20.00 10.40
M STRIP ASSY-FR BUMPER UPR 1 X MM					1.00 29.00 20.00 23.20
M ORNAMENT-KIA NO.115					1.00 32.00 20.00 25.60
M MIRROR ASSY-OUTSIDE RR VIEW, LH - CUT					1.00 419.00 20.00 335.20
M W/STRIP ASSY-FR DR BELT O/S LH - CUT					1.00 58.00 20.00 46.40
M W/STRIP ASSY-RR DR BELT O/S LH - CUT					1.00 89.00 20.00 71.20

SURVEYOR NAME: Steve CLKK) 5/2/21, 5.00pm
 SURVEYOR SIGNATURE: OO NM ALL
EXOS - ?

DATE: P/P
By BCL SM
5 days

Confirm & accepted by

LYK Auto Consultants hereby confirm the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation

Authorized signatory and company stamp

7% GST on	Nett 4,678.40	4,678.40
	4678.40	327.49
Total Payable		5,005.89

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.