



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 05.02.2021
Emailed : 10.03.2021, 4.25pm
Date Survey : 05.02.2021

VEHICLE NO : SMC 7198 Y
MODEL : KIA FORTE K3 1.6 A L
WIP : 28632

Material	:	\$	<u>478.40</u>
Labour	:	\$	<u>2,820.00</u>
Sub-Total	:	\$	<u>3,298.40</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>2,998.40</u>
GST 7%	:	\$	<u>209.89</u>
Grand Total	:	\$	<u>3,208.29</u>
Finalise By/Date	:		<u>LOI / 10/03/2021</u>

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Tan Kwong Luck Robert
	Reg No/Reg Date	SMC7198Y / 19/07/2018
	Date In/Mileage	08/02/2021/ 31234
	Chassis/Package	KNAFJ411MJ5762532
	Engine No	G4FGHH692768
	Make/Model	KIA/FORTE K3 1.6 A L 189
08/02/2021	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	09/03/2021/ 16:34	BLE	260 / AiTing	28632

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE LH WING MIRROR, REPAIR & ALIGN LH FRONT FENDER, LH FRONT DOOR, LH REAR DOOR, FRONT BUMPER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 800.00
E PNT98000 RESPRAY ON FRONT BUMPER, LH FRONT FENDER, LH FRONT DOOR, LH REAR DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1400.00
M SUNDRY REPLACE LH FRONT TIRE, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING				✓ 30.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT				✓ 120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				✓ 40.00
M SUNDRY SUNDRIES				✓ 20.00
S TYRESALES2 SUPPLY LH FRONT TIRE				✓ 260.00
X EXC EXCESS				-300.00
X ORNAMENT-KIA NO.115	1.00	✓ 32.00	20.00	25.60
X MIRROR ASSY-OUTSIDE RR VIEW,LH	1.00	✓ 419.00	20.00	335.20
X W/STRIP ASSY-FR DR BELT O/S LH	1.00	✓ 58.00	20.00	46.40
X W/STRIP ASSY-RR DR BELT O/S LH	1.00	✓ 89.00	20.00	71.20
Z TEXT AIG OD CLAIM DOA : 05.02.21 SURVEYOR STEVE LKK 05.02.21 POLICY NO: 1800083518				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	478.40	Nett	2,998.40
Labour	2,470.00	7% GST on	2998.40
Standard Menu	0.00		
Specialist Job	260.00	Total Payable	3,208.29
Diagnostics Job	0.00		
Sundry/Others	-210.00		
Total(w/o GST)	2,998.40		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CERATO/FORTE../2018/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



EPS



AIRBAG



ABS/ESC

5/5

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver. M-E-K-01-00-0238

VCI Ver. 02.49

ECU Ver. M-E-K-01-00-0179

OS Ver. Android 10

Work Order: R001353
License: SMC7198Y
Technician: 214 THAM
Mileage: 31234
Date 16.2.21 14:49

Kia : Cerato/Forte : 2013-19 (YD/YDm)

Front : Left

Actual	Before	Specified Range
-0°24'	-0°24'	-0°52' 0°08'
3°51'	3°51'	3°31' 4°31'
0°03'	0°07'	-0°03' 0°09'
13°48'	13°49'	13°06' 14°06'
13°25'	13°25'	12°14' 14°14'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°42'	-0°42'	-0°52' 0°08'
4°08'	4°08'	3°31' 4°31'
0°01'	-0°03'	-0°03' 0°09'
15°02'*	15°02'*	13°06' 14°06'
14°20'*	14°20'*	12°14' 14°14'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°19'	0°18'	
-0°17'	-0°17'	
-1°14'	-1°13'	
0°05'	0°04'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°27'	-1°28'	-2°00' -1°00'
0°15'	0°16'	0°00' 0°27'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°42'	-1°42'	-2°00' -1°00'
0°14'	0°14'	0°00' 0°27'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°14'	0°14'	
0°29'	0°30'	0°00' 0°54'
0°00'	0°01'	

* This value is not within specification. Tire wear, handling and safety problems may result.