

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Low

Date: 15 Feb 2021

**Preliminary Advice**

Insured Vehicle No	: SMF4183T	Accident Date	: 03/02/2021
TP Vehicle No	: SLQ6977K	Assignment Date	: 05/02/2021
Make	: HONDA SHUTTLE	Est. Duration of Repair	: 23
Date of Inspection	: 08/02/2021		
Inspection At	: YEE AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	48,974.60
Revised Amount	:S\$	23,800.25
Check Items (Estimated)	:S\$	13,860.70
Total	:S\$	37,660.95
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :