



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

Estimate No: ES2100016

Date: 04 Feb 2021

Policy No:

Veh Reg No: SLQ6977K

ATTN: Motor Claim Department

Make/Model: HONDA SHUTTLE 1.5G CVT

Your Ref No: -

Chassis No: GK81007749

Claim Type: Third Party

Engine No: L15B3539067

Accident Date: 03/02/2021

Reg. Date: 19/07/2017

TP Veh Reg No: SMF4183T

Estimate Repair Cost to Vehicle No :SLQ6977K

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 FRONT NUMBER PLATE	60.00	1 PC	CM 60.00	45.50
2 REAR NUMBER PLATE	60.00	1 PC	CM 60.00	45.50
3 REAR WINDSCREEN SEALANT	60.00	1 PC	na 60.00	40.50
4 REVERSE SENSORS	300.00	1 PC	na 300.00	200.50
5 REVERSE CAMERA	350.00	1 PC	na 350.00	X
6 REAR WINDSCREEN SOLAR FILM	280.00	1 PC	na 280.00	X
			1,110.00	1,110.00
Spare Parts				
7 AIRCON CONDENSER	937.00	1 PC	BT 937.00	✓
8 AIRCON FAN MOTOR	434.00	1 PC	na 434.00	X
9 BRACE PANEL	117.00	1 PC	na 117.00	X
10 FOG LAMP COVER - LH	145.50	1 PC	na 145.50	X
11 FOG LAMP COVER - RH	145.50	1 PC	na 145.50	X
12 FRONT BONNET	1,250.00	1 PC	BT 1,250.00	✓
13 FRONT BONNET HINGE - LH	85.50	1 PC	na 85.50	X
14 FRONT BONNET HINGE - RH	85.50	1 PC	na 85.50	X
15 FRONT BONNET INSULATOR	260.00	1 PC	na 260.00	X
16 FRONT BONNET INSULATOR CLIPS	50.00	1 SET	na 50.00	X
17 FRONT BONNET LOCK	165.00	1 PC	DI 165.00	✓
18 FRONT BONNET RUBBER	75.10	1 PC	na 75.10	✓
19 FRONT BONNET STOPPER	20.00	2 PC	na 40.00	X
20 FRONT BUMPER	1,115.60	1 PC	na 1,115.60	✓
21 FRONT BUMPER BRACKET - LH	80.50	1 PC	na 80.50	X
22 FRONT BUMPER BRACKET - RH	80.50	1 PC	na 80.50	X
23 FRONT BUMPER CLIPS	60.00	1 SET	na 60.00	✓
24 FRONT BUMPER GRILLE CENTRE	365.50	1 PC	CM 365.50	na
25 FRONT BUMPER REINFORCEMENT	400.00	1 PC	BT 400.00	na
26 FRONT BUMPER SIDE RETAINER - LH	75.00	1 PC	DI 75.00	✓
27 FRONT BUMPER SIDE RETAINER - RH	75.00	1 PC	DI 75.00	✓
28 FRONT BUMPER SPONGE - LH	32.50	1 PC	na 32.50	X
29 FRONT LOGO	95.10	1 PC	na 95.10	✓
30 FRONT BUMPER TOWING COVER - RH	48.50	1 PC	na 48.50	X
31 FRONT FENDER - LH	490.20	1 PC	na 490.20	X
32 FRONT FENDER - RH	490.20	1 PC	na 490.20	✓
33 FRONT FENDER INNER SHIELD	195.10	1 SET	na 195.10	X
34 FRONT FENDER INNER SHIELD CLIP - RH	50.00	1 SET	na 50.00	X

Not Notation

L1 Reg 822,000/

Recovery After Pain

23 days



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 03/02/2021

TP Veh Reg No: SMF4183T

Estimate No: ES2100016

Date: 04 Feb 2021

Policy No:

Veh Reg No: SLQ6977K

Make/Model: HONDA SHUTTLE 1.5G
CVT

Chassis No: GK81007749

Engine No: L15B3539067

Reg. Date: 19/07/2017

Estimate Repair Cost to Vehicle No :SLQ6977K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 FRONT GRILLE CHROME COVER	205.50	1 PC	CM 205.50	✓
36 FRONT GRILLE	299.00	1 PC	CM 299.00	✓
37 FRONT HEADLAMP LOWER BRACKET - LH	92.50	1 PC	BH 92.50	✓
38 FRONT HEADLAMP LOWER BRACKET - RH	92.50	1 PC	BH 92.50	✓
39 FRONT SUPPORT PANEL 631.20	807.10	1 PC	BH 807.10	✓
40 FRONT SUPPORT PANEL TOP COVER	156.00	1 PC	SH 156.00	X
41 FRONT SUPPORT PANEL TOP COVER CLIP	40.00	1 SET	SH 40.00	X
42 HEAD LAMP - LH	1,875.10	1 PC	mycm 1,875.10	✓
43 HEAD LAMP - RH	1,875.10	1 PC	mycm 1,875.10	✓
44 HORN	65.00	1 PC	SH 65.00	X
45 RADIATOR ASSY	950.10	1 PC	SH 950.10	✓
46 RADIATOR FAN BLADE	65.00	1 PC	SH 65.00	X
47 RADIATOR FAN COWLING	180.00	1 PC	SH 180.00	X
48 RADIATOR FAN MOTOR	405.50	1 PC	SH 405.50	X
49 RADIATOR TOP HOSE	58.00	1 PC	SH 58.00	X
50 RADIATOR WATER COOLANT	50.00	1 PC	SH 50.00	25m
51 WASHING TANK	171.50	1 PC	SH 171.50	X
52 REAR CHASSIS MEMBER -LH 780.50	950.80	1 PC	BH 950.80	✓
53 REAR CHASSIS MEMBER -RH	950.80	1 PC	950.80	✓
54 REAR FENDER - LH	1,259.50	1 PC	R 1,259.50	X
55 REAR FENDER - RH 1011.90	1,259.50	1 PC	BH 1,259.50	✓
56 REAR FENDER GLASS MOULDING - LH	89.20	1 PC	SH 89.20	X
57 REAR FENDER GLASS MOULDING - RH	89.20	1 PC	SH 89.20	✓
58 REAR FENDER GLASS SEALANT - LH	50.00	1 PC	SH 50.00	X
59 REAR FENDER GLASS SEALANT - RH	50.00	1 PC	SH 50.00	40m
60 REAR TAILGATE ABSORBER - LH	220.50	1 PC	SH 220.50	✓
61 REAR TAILGATE ABSORBER - RH	220.50	1 PC	SH 220.50	✓
62 REAR TAILGATE LAMP - LH	460.50	1 PC	CM 460.50	✓
63 REAR TAILGATE LAMP - RH	460.50	1 PC	CM 460.50	✓
64 REAR FENDER LOWER INNER SHIELD - LH	150.00	1 PC	SH 150.00	X
65 REAR FENDER LOWER INNER SHIELD - RH	150.00	1 PC	SH 150.00	X
66 REAR FENDER INNER SHIELD CLIP - LH	40.00	1 SET	SH 40.00	X
67 REAR FENDER INNER SHIELD CLIP - RH	40.00	1 SET	SH 40.00	X
68 REAR FENDER INNER TRIMBOARD TOP - LH 312.10	415.10	1 SET	SH 415.10	✓
69 REAR FENDER INNER TRIMBOARD TOP - RH 312.10	415.10	1 SET	CM 415.10	✓
70 REAR AIR VENT - LH	60.50	1 PC	SH 60.50	X
71 REAR BUMPER 1150.40	1,422.50	1 PC	BH 1,422.50	✓
72 REAR BUMPER BRACKET - LH	98.10	1 PC	BH 98.10	✓



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 03/02/2021

TP Veh Reg No: SMF4183T

Estimate No: ES2100016

Date: 04 Feb 2021

Policy No:

Veh Reg No: SLQ6977K

Make/Model: HONDA SHUTTLE 1.5G
CVT

Chassis No: GK81007749

Engine No: L15B3539067

Reg. Date: 19/07/2017

Estimate Repair Cost to Vehicle No :SLQ6977K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
73 REAR BUMPER BRACKET - RH	98.10	1 PC	Bt 98.10	✓
74 REAR BUMPER CLIPS	40.00	1 SET	Me 40.00	✓
75 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	Di'y 65.20	✓
76 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	Di'y 65.20	✓
77 REAR BUMPER TOW HOOK COVER	35.50	1 PC	Di'y 35.50	✓
78 REAR EXHAUST MUFFLER	650.90	1 PC	Bt 650.90	✓
79 REAR FENDER INNER TRIMBOARD - LH	485.00	1 PC	ngcm 485.00	✓
80 REAR FENDER INNER TRIMBOARD - RH	485.00	1 PC	Di'y 485.00	✓
81 REAR TAILGATE 1193.70	1,572.50	1 PC	Bt 1,572.50	✓
82 REAR TAILGATE INNER TRIMBOARD 243.80	475.00	1 PC	Di'y 475.00	✓
83 REAR TAILGATE LOCK	265.10	1 PC	Im 265.10	✓
84 REAR TAILGATE OUTER GARNISH	285.10	1 PC	wap 285.10	✓
85 REAR TAILGATE WEATHERSTRIP	193.70	1 PC	not wt 193.70	502in 96.85in
86 REAR TAILLAMP PANEL - LH	185.00	1 PC	Bt 185.00	✓
87 REAR TAILLAMP PANEL - RH	185.00	1 PC	Bt 185.00	✓
88 REAR WHEEL PANEL TOOL BOX	456.20	1 PC	Di'nd 456.20	✓
89 REAR WHEEL PANEL TRIMBOARD 265	310.00	1 PC	Di'nd 310.00	✓
90 REAR WINDSCREEN MOULDINGS	110.50	1 PC	Me 110.50	✓
91 REAR WINDSCREEN MOULDING LOWER	90.10	1 PC	Me 90.10	✓
92 SPARE WHEEL PANEL 1072.50	1,135.90	1 PC	Bt 1,135.90	✓
93 TAIL LAMP LH 422.50	585.50	1 PC	CM 585.50	✓
94 TAIL LAMP RH 422.50	585.50	1 PC	Bu 585.50	✓
95 REAR TAILLAMP LOWER BRACKET - LH	48.50	1 PC	Di'y 48.50	✓
96 REAR TAILLAMP LOWER BRACKET - RH	48.50	1 PC	Di'y 48.50	✓
97 REAR BUMPER REFLECTOR - LH 64	195.00	1 PC	scr 195.00	✓
98 REAR BUMPER REFLECTOR - RH 64	195.00	1 PC	CM 195.00	✓
99 REAR END PANEL TOP GARNISH CLIPS	40.00	1 PC	Me 40.00	✓
100 REAR END PANEL TOP GARNISH	250.10	1 PC	Bu 250.10	✓
101 REAR TAILGATE 'LOGO' EMBLEM 65	125.00	1 PC	Me 125.00	✓
102 REAR TAILGATE EMBLEM 'SHUTTLE'	95.50	1 PC	Me 95.50	✓
103 REAR TAILGATE UPPER HINGE - LH	125.00	1 PC	Di'y 125.00	✓
104 REAR TAILGATE UPPER HINGE - RH	125.00	1 PC	Di'y 125.00	✓
105 REAR WIPER BLADE	45.00	1 PC	su 45.00	X
106 REAR WIPER MOTOR	495.00	1 PC	Im 495.00	✓
107 REAR WIPER PLATE ARM	95.10	1 PC	su 95.10	X
108 REAR NUMBER PLATE LAMP - LH	55.50	1 PC	su 55.50	X
109 REAR NUMBER PLATE LAMP - RH	55.50	1 PC	su 55.50	X
110 REAR TAILGATE WINDSCREEN 1120.80 Shattow	1,450.10	1 PC	1,450.10	✓



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 03/02/2021
TP Veh Reg No: SMF4183T

Estimate No: ES2100016
Date: 04 Feb 2021
Policy No:
Veh Reg No: SLQ6977K
Make/Model: HONDA SHUTTLE 1.5G CVT
Chassis No: GK81007749
Engine No: L15B3539067
Reg. Date: 19/07/2017

Estimate Repair Cost to Vehicle No :SLQ6977K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
111 REAR TAILGATE TOP OPENING SWITCH	185.50	1 PC	CM 185.50	2
112 REAR BUZZER SENSOR	189.20	1 PC	CM 189.20	2
113 REAR FENDER INNER PANEL - LH	1,150.50	1 PC	R 1,150.50	X
114 REAR FENDER INNER PANEL - RH	1,150.50	1 PC	R 1,150.50	X
115 REAR TAILLAMP LOWER PANEL - LH	165.00	1 PC	R 165.00	2
116 REAR TAILLAMP LOWER PANEL - RH	165.00	1 PC	R 165.00	2
117 REAR BUMPER LOWER SHIELD - LH	175.10	1 PC	S 175.10	X
118 REAR BUMPER LOWER SHIELD - RH	175.10	1 PC	S 175.10	X
119 REAR BUMPER LOWER SHIELD CLIP - LH	40.00	1 PC	nn 40.00	X
120 REAR BUMPER LOWER SHIELD CLIP - RH	40.00	1 PC	nn 40.00	X
121 REAR TAIL GATE STOPPER RUBBER - LH	35.00	1 PC	R 35.00	X
122 REAR TAIL GATE STOPPER RUBBER - RH	35.00	1 PC	R 35.00	X
123 REAR BUMPER SIDE SPONGE - LH	180.00	1 PC	CM 180.00	2
124 REAR BUMPER SIDE SPONGE - RH	180.00	1 PC	CM 180.00	2
125 REAR BUMPER TOWING COVER	55.00	1 PC	Hyundai 55.00	X
126 REAR AUTO LOCK CONTROL SENSOR	160.00	1 PC	160.00	7X SVC
127 REAR END PANEL	480.50	1 PC	R 480.50	✓
128 REAR END PANEL INNER	NSP 420.10	1 PC	R 420.10	X
129 REAR END PANEL LOWER GARNISH	295.20	1 PC	CM 295.20	2
130 REAR END PANEL INNER LOWER GARNISH	210.10	1 PC	Return 210.10	2
			40,974.60	40,974.60
Labour				
131 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,800.00	1 JOB	2,800.00	2200d
132 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,500.00	1 JOB	2,500.00	2200d
133 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	300.00	1 JOB	300.00	180d
134 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	120d
135 TO REMOVE/REFIT PASSENGER SEAT, FENDER GARNISHES TO FACILITATE REPAIRS.	250.00	1 JOB	250.00	120d
136 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	150.00	1 PC	150.00	60d
137 TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	40d
138 COMPUTER DIAGNOSTIC RESET	300.00	1 PC	nn 300.00	X
139 WHEEL ALIGNMENT	120.00	1 T	120.00	60d
140 AIRCON GAS	120.00	1 JOB	120.00	700d
			6,890.00	6,890.00



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 03/02/2021
TP Veh Reg No: SMF4183T

Estimate No: ES2100016
Date: 04 Feb 2021
Policy No:
Veh Reg No: SLQ6977K
Make/Model: HONDA SHUTTLE 1.5G
CVT
Chassis No: GK81007749
Engine No: L15B3539067
Reg. Date: 19/07/2017

Estimate Repair Cost to Vehicle No :SLQ6977K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 48,974.60
			Add GST @ 7%	3,428.22
			Total Amount Payable	<u>S\$ 52,402.82</u>

TOTAL: SINGAPORE DOLLAR FIFTY TWO THOUSAND FOUR HUNDRED AND TWO AND CENTS EIGHTY TWO ONLY

For Yee Auto Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:


AUTHORISED SIGNATURE