



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 05.02.2021
Emailed : 18.02.2021, 11.30am
Date Survey : 08.02.2021

VEHICLE NO : SMN 6181 T
MODEL : MIT OUTLANDER 2.0
WIP : 62698

Material	:	\$	<u>1,368.29</u>
Labour	:	\$	<u>2,790.00</u>
Sub-Total	:	\$	<u>4,158.29</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,158.29</u>
GST 7%	:	\$	<u>291.08</u>
Grand Total	:	\$	<u>4,449.37</u>
Finalise By/Date	:	<u>LOI / 18/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 08/02/2021	Cust No/Name	KCV11903/Mr Tan Keng Boo
	Reg No/Reg Date	SMN6181T*DC17/ 21/08/2019
	Date In/Mileage	08/02/2021/ 24788
	Chassis/Package	GF7W0601723 /FTP
	Engine No	4J11BD7746
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	18/02/2021/ 09:52	BLC	260 / AiTing	62698		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR TAILGATE, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							✓ 675.00
E PNT98000 RESPRAY ON REAR BUMPER, TAILGATE, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓ 1050.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR							✓ 60.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM							✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE							✓ 120.00
M SUNDRY SUNDRIES							✓ 20.00
M SUNDRY SUPPLY C&C LOGO							✓ 40.00
E PNT88000 REPAIR REAR END PANEL → Supp.							225.00
E PNT98000 RESPRAY ON REAR END PANEL → Supp.							350.00
S SPECIALISTJOB SUPPLY ONE SET OF REVERSE SENSOR → Supp.							220.00
X BRKT,R/BMPR FACE SIDE,RH				1.00	✓ 12.00	23.00	9.24
X BRKT,R/BMPR FACE SIDE,LH				1.00	✓ 12.00	23.00	9.24
X FACE,RR BUMPER				1.00	✓ 807.00	23.00	621.39
X EXTENSION,RR BUMPER				1.00	✓ 292.00	23.00	224.84
X MOULDING,RR BUMPER,RH				1.00	✓ 106.00	23.00	81.62
X MOULDING,RR BUMPER,LH				1.00	✓ 106.00	23.00	81.62
X MARK,OUTLANDER				1.00	✓ 95.00	23.00	73.15
X BUZZER,KEYLESS OPERATIO,RR				1.00	? 91.00	23.00	70.07
X ANT,KEYLESS OPERATION,RR				1.00	? 96.00	23.00	73.92
X MOULDING,RR WHEEL ARCH,LH → Supp.				1.00	160.00	23.00	123.20

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 08/02/2021	Cust No/Name	KCV11903/Mr Tan Keng Boo
	Reg No/Reg Date	SMN6181T*DC17/ 21/08/2019
	Date In/Mileage	08/02/2021/ 24788
	Chassis/Package	GF7W0601723 /FTP
	Engine No	4J11BD7746
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/02/2021/ 09:52	BLC	260 / AiTing	62698

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT AIG OD CLAIM. DOA : 05.02.21 SURVEYOR STEVE LKK 08.02.21 POLICY NO : 1900149633 Pro Forma <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,368.29		Nett	4,158.29
Labour	2,510.00	7% GST on	4158.29	291.08
Standard Menu	0.00			
Specialist Job	220.00		Total Payable	4,449.37
Diagnostics Job	0.00			
Sundry/Others	60.00			
Total(w/o GST)	4,158.29			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMN 6181 T**

Materials

Cost (\$)

1	Moulding, RR wheel arch, LH	160.00	✓ <i>nel</i>
Total		160.00	
Less 23%		36.80	
Total Materials		123.20	

Labour

Cost (\$)

1	Repair Rear end panel	225.00	✓
2	Respray rear end panel	350.00	✓
3	Supply one set of reverse sensor	220.00	✓ <i>BR</i>
Total Labour		795.00	
Taxable Amount		918.20	
7% GST		64.27	
Grand total		982.47	

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

[Signature]
LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501

SMNG181T

After using part-3x not unit to Base all Base Land
to Job Done.

2021.02.16

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

All DTCs

2021.02.16

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition	
	MPI/GDI/DIESEL	GAS_0E640000		No DTCs			
	Auto Stop & Go (AS&G)	ASG_25080000		No DTCs			
	AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs			
	AUTO CRUISE	GAS_0E640000		Non-target System			
	4WS/Electric Power Steering	EPS_45880040		No DTCs			
	ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs			
	SRS-AIR BAG	ORC_81047302		No DTCs			
	Air Conditioner	AC_80080011		No DTCs			
	ETACS	ETACS_83040801		No DTCs			
	Meter	MTR_84084001		No DTCs			
	Steering Angle Sensor	GS_SAS_47000100		Non-target System			
	AND	AND_8C080002		Non-equipped System or Communication Error			
	AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error			
	LIN	ETACS_83040801		Non-target System			
	Power Gate	ETG_92080000		Non-equipped System or Communication Error			

All DTCs

2021.02.16

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Key/less	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	