

ASS. REC. BY: Sun Pin

REF: CS/CTI 21001799/QVf3.

Veteran

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Veh No: SFZ 8008T Yr Regn: 28/04/2011

Estimated Cost: \_\_\_\_\_

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or \_\_\_\_\_

To Inspect Vehicle No: \_\_\_\_\_

Make: BMW 740L c.c. 2974

at Workshop m/s \_\_\_\_\_

Colour: Black A/C: Insured / Std / NI / NA

of \_\_\_\_\_

Sp. Reading: 147441 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: -

Policy No. DMPRSN W00151792000

C/No: WBAKB42020CF83652

Claims No. SNM 21D200497 / COI / TAN KL

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: 500

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Make of Veh: \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)

Tyre Size: F: 245/50 R18  
R: 245/50 R18

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

D.O.A. 20/01/2021 D.O.I. 09/02/2021

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Survey held at Auto Inssure.

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or \_\_\_\_\_

CA / REV / REP. / 24 HRS

The U/C / Chassis frame / Body Structure affected due to collision.

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	MR: 50,000
	PR: 43,054
	NV: 6,946
22/4/21	LS 6000 confirmed by email (Red 9994.02, 629)
	*Already inform workshop CoR not exceed \$6,000

Date/Time, File Pass to?  : Preli. Report  
1)  : Final Report

Days Of Repair: 7  
Resurvey No. of Trip: 1

Date/Time, File Return to?  
2) 23/4 - typist

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

Survey Fee:	
Transportation:	
_____ S + RS. _____ SI	
Photos	
Others	
TOTAL	

Report Format: Merimen  
Lump Sum / I.B.A. / 6000

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	290H
Vehicle Details	
Vehicle No.:	SFZ8008T
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jan 2021
Vehicle Make:	B.M.W.
Vehicle Model:	740LI 3.0L A/T ABS D/AB 2WD 4DR HID SR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	15137716N54B30A
Chassis No.:	WBAKB42020CY83652
Maximum Power Output:	240.0 kW (321 bhp)
Open Market Value:	\$82,981.00
Original Registration Date:	29 Apr 2011
First Registration Date:	29 Apr 2011
Transfer Count:	2
Actual ARF Paid:	\$82,981.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2021
PARF Rebate Amount:	\$41,490.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,010.00
COE Rebate Amount:	\$1,564.00
<b>Total Rebate Amount:</b>	<b>\$43,054.00</b>

The information contained herein is correct as at 27 Jan 2021

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 21/01/2021 12:59 (SGT)  
Date of Accident ..... 20/01/2021 13:50 (SGT)  
Exact Location of Accident ..... Marsiling Ln, Singapore  
Additional Location Information ..... ALONG MARSILING LANE OPEN CARPARK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SFZ8008T

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... DEVENDARAN NAIDU S/O KRISHNAN NATHAN  
NRIC No ..... SXXXX290H  
Email Address ..... DNAIDU88@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-81808008  
Alternative Phone No ..... (Office) +65-81808008

### VEHICLE PARTICULARS

Manufacturer ..... BMW  
Model ..... 740li  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car

### INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... DMPCSNW00151792000  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... SANTHI D/O RETNAM MOORTY  
NRIC No ..... SXXXX971D  
Date Of Birth ..... 29/10/1971  
Occupation ..... Indoor

Date Of Driving Pass .....	29/05/1992
Driving experience .....	28 YEARS AND 8 MONTHS
Gender .....	Female
Mobile Number .....	(Phone) +65-96635292
Alt. Phone Number .....	-
Email Address .....	SANTHI88@GMAIL.COM
Address .....	NO.88 JALAN BUMBONG
Address complement .....	-
Postcode .....	739903
Is the driver the policyholder? .....	No
If No, Relationship of the Driver with the Insured .....	Spouse
Does Driver Own Other Vehicles? .....	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver .....	SGT88J
Insurance Company of Other Vehicle Owned by Driver .....	Etiqua

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Head on collision
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	Yes
Was any injured conveyed to hospital by ambulance? .....	No
Was any other material or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	Yes
Police Station Name .....	Choa Chu Kang Neighbourhood Police Centre
Police Station Phone No .....	(Phone) +65-18007659999
Alt. Police Station Phone No .....	(Fax) +65-67644104
Police Station Address .....	No 20 Choa Chu Kang Street 52 #01-02 Singapore 689286
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

PLS REFER TO POLICE REPORT NO:T/20210120/2118.

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	Yes
Was there any audio recorded? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	YN1662M
Vehicle Manufacturer .....	-
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Commercial vehicle
Name of Driver .....	-
Contact Number .....	-


Address ..... -  
Address complement ..... -  
Postcode ..... -  
Insurance Company Name ..... -  
Nature Of Damage ..... -  
Details of property damaged in accident ..... -  
No. Of Passenger (Including Driver) ..... -

### INJURED PERSONS DETAILS

INJURED 1

Name of injured person ..... -  
Address ..... -  
Address Complement ..... -  
Post Code ..... -  
Approximate Age Years Old ..... -  
Injuries Sustained ..... -  
Injured person in which vehicle? ..... -  
Were seat belts worn? ..... -  
Was this injured conveyed to hospital by ambulance? ..... -

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer to Police Report NO: T/20210120/2118.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/Fin No.:

**Auto Insure Pte. Ltd**  
**6 Marsiling Lane**  
**739145**



**Insurer Reference: SFZ8008T**  
**Repairer Reference: M1477 / SFZ8008T**  
**Date calculated: 01/02/2021 10:22 AM**

**Full Report**  
**Registration: SFZ8008T**  
**Printed: 01/02/2021 10:22 AM**

## Summary Information

---

### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Min Seng Chong	Currency:	SGD
Claim Reference:	SFZ8008T	Date of Incident:	20/01/21
Estimated Repair Time:	8	Hire Car Start:	
Actual Repair Days:	8	Hire Car End:	

## Vehicle Details

---

### Vehicle

Manufacturer:	BMW
Model:	7-SERIES F01/02
Sub Model:	740 LI
Model Sheet Number:	01 06 11
Registration:	SFZ8008T
VIN number:	WBAKB42020CY83652
Odometer:	146375

### Model Specs

FROM 09/2010	INTER LIGHT AMBIENCE	AIR CON AUTO 4-ZONES	REAR SCREEN-SUNBAND
DVD CHANGER	DIP/FOLD MIRROR	SURROUND VIEW	NAVIG-SYST PROFESS
HI-FI SPEAKER SYSTEM	COMFORT ACCESS SYST	AUTO TAILGATE CONTR	SOFT CLOSE AUTOMATIC
DAKOTA LEATHER TRIM	LUMBAR SUPPORT	FRONT COMFORT SEATS	HEATED FRONT SEATS
HEATED REAR SEAT	SIDE ROLLER BLIND	REARVIEW CAMERA	NOBLE WOOD FINELINE
PARK DISTANCE CONT	SPORT S-WHEEL LEATH	AUTOMATIC 6-SPEED	INTEGRAL ACTIVE STRG
DYNAMIC DRIVE	TYRES 245/50 WR 18	WHEELS 8J X 18 ALLOY	ROOF MLDG VEH COLOUR
ELECTRIC SUNROOF	VERSION HOT COUNTRY	TWO COAT METALLIC	

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All   
Underbody



## Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
41 52 580	R + R RIGHT REAR DOOR		4.0	14.00
41 52 504	ADJUST R/R DOOR		2.0	7.00
41 52 501	RENEW R/R DOOR (REMOVED)		31.0	108.50
51 42 504)	RENEW R/R DOOR TRIM (REMOVED)		1.0	3.50
41 35 111	RENEW R/R SIDE PANEL		200.0	700.00
	INCLUDES: R + R REAR SEAT, SEAT BACKREST, TAILGATE, REAR WINDOW, TAIL LAMP, BUMPER, BUMPER CARRIER, BUMPER GUIDE, SILL MOULDING, LUGGAGE COMPARTMENT TRIM, REAR SILL COVER STRIP, UPPER C-PILLAR TRIM AND REAR DOOR			
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)		1.0	3.50
66 20 603	ADD/WORK PARK DISTANCE CONTROL		3.0	10.50
36 11 512	R + R R/R WHEEL/TYRE		6.0	21.00
36 11 500	TYRE PUNCTURE INITIALIZE DISPLAY		1.0	3.50
00 00 556	VEHICLE CHECK (BY VEHICLE DIAGNOSTIC SYSTEM)		3.0	10.50
66 53 515	CALIBRATE BACKUP CAMERA (AFTER VEHICLE TEST)		1.0	3.50
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>21.10</b>	<b>253.0</b>
<b>Total of Labour</b>				<b>885.50</b>

# Paint

Paint Work		Time Basis 12 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
99 52 548	R/R DOOR PAINTING STAGE 2	19.0	66.50
99 21 611	R/R OUTER HANDLE PAINTING STAGE 2	2.0	7.00
99 69 547	REAR BUMPER PAINTING STAGE 2	15.0	52.50
99 36 529	R/R SIDE PANEL PAINTING STAGE 3	28.0	98.00
99 51 538	RIGHT FRONT DOOR PAINTING STAGE 1	10.0	35.00
99 37 509	RIGHT SILL PAINTING STAGE 1	15.0	52.50
99 31 542	RIGHT A-PILLAR PAINTING STAGE 1	5.0	17.50
99 21 509	RIGHT B-PILLAR PAINTING STAGE 1	10.0	35.00
99 36 509	R/R SIDE PANEL PAINTING STAGE 1	11.0	38.50
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	22.0	77.00

Total Paint	Hrs	WU	Price SGD
	11.40	137.0	479.50

Material Cost - Paint	Price SGD
New Part Painting	138.50
Repair Painting	38.61
Surface-/Blend Paint	127.44
Material-constant Metal	13.47
<b>Total</b>	<b>318.02</b>

# Spare Parts

					prices as at 2021-01-18	
Code	Description	Part Number	Part Source		Price SGD	
3162	CLEANER R1 RR SCREEN	83 19 2 211 217	Original	X SVC		0.00
3172	LOWER R/SCREEN TRIM	51 31 7 184 569	Original	? / NEC		78.00
3526	R/C-PILLAR REINF	41 21 7 275 599	Original	X SVC		0.00
1782	R/R DOOR	41 00 7 203 982	Original	/ PB		2,160.00
1878	R/R DOOR LOCK	51 22 7 185 688	Original	? X SVC		610.00
2012	R/R DOOR TRIM	51 42 9 161 788	Original	? X SVC		4,020.00
2622	R/R OUT BUMPER BRKT	51 12 7 183 886	Original	? X SVC		230.00
1866	R/R OUTER HANDLE	51 21 7 231 934	Original	/ SCR		720.00
1962	R/R OUT WINDOW MLDG	51 35 7 179 122	Original	? X SVC		130.00
3482	R/R SIDE PANEL	41 21 7 204 488	Original	/ CR4		2,040.00
9552	R/R WHEEL	36 11 6 775 777	Original	/ SCR		1,170.00
4202	R/R W-HOUSE COVER	51 71 7 185 270	Original	? X SVC		150.00
3516	R/S/PANEL CLEANER R1	83 19 2 211 217	Original	X		0.00
3512	R/S/PNL ADHESIVE K5A	83 19 2 158 654	Original	X	} SVC	0.00
3514	R/S/PNL ADHESIVE K5B	83 19 2 157 298	Original	X		0.00
3508	R/SIDE PANEL REP KIT	USE SINGLE PARTS	Original	X		0.00
3524	R/SILL REINFORCEMENT	41 21 7 275 568	Original	X		0.00
2583	REAR BUMPER COVER	51 12 7 209 926	Original	X R		1,320.00
3160	REAR SCREEN BOND KIT	83 19 2 289 285	Original	X	} SVC	0.00
3164	REAR SCREEN BUFFER	51 31 2 996 980	Original	X		0.00
3520	S/PANEL B/RIVET N3	83 19 0 301 421	Original	X		0.00
3518	S/PNL STAMP RIVET N4	83 19 2 457 307	Original	X		0.00

Code	Description	Part Number	Part Source	Price SGD
4193	SEAM SEALANT	83 42 2 409 985	Original <i>X Svc</i>	0.00
3522	SIDE PANEL EMC SCREW	83 19 0 301 639	Original <i>X Svc</i>	0.00
3171	UP/COVER REAR SCREEN	51 31 7 184 568	Original <i>/Nec.</i>	78.00

f: OEM Parts	<b>Savings</b>	0.00
n: Non-OEM Parts	<b>Subtotal</b>	12,706.00
u: Used parts	<b>Total</b>	12,706.00

### Extras

Code	Description	Price SGD
1000	ALIGNMENT&BALANCING WHEEL	<i>60</i> 80.00*
1001	BODY SEALANT REAR FENDER RH <i>/NA</i>	<i>30</i> 80.00*
1002	SEALANT REAR WINDSCREEN <i>/Nec</i>	<i>40</i> 100.00*
<b>Total Extras</b>		260.00

### Final Calculation

	SGD	SGD
<b>Parts</b>	12,706.00	
<b>Total Parts</b>		12,706.00
<b>Labour Time Base 12 WU/h</b>		
Total 253.0 WU X 42.00 SGD/h	885.50	
<b>Total of Labour</b>		885.50
<b>Total Of Extras</b>		260.00
<b>Paint Work Time Base 12 WU/h</b>		
Labour Cost 137.0 WU X 42.00 SGD/h	479.50	
Material Cost	318.02	
<b>Total Paint Including Material</b>		797.52
<b>Repair Cost Excludes GST</b>	<i>15,994.02</i>	14,649.02
GST (+7.00%)		1,025.43
<b>Repair Cost Included GST</b>		15,674.45
<b>Deductions (Excludes GST)</b>		
Deduction For Excess	-1,500.00	
<b>Total Of Deductions (Excludes GST)</b>		-1,500.00
<b>Grand Total Excludes GST</b>		13,149.02
GST (+7.00%)		920.43
<b>Grand Total Included GST</b>		14,069.45

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Repair day 7 days*  
*LIS*  
*After paint photo*  
*Excess \$500*  
*REV - not Authorise.*

*Sun Pin (LKK)*  
*09/02/2021*

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

---

**No assessment notes entered.**

**Auto Insure Pte. Ltd**  
**6 Marsiling Lane**  
**739145**



**Insurer Reference: SFZ8008T**  
**Repairer Reference: M1477 / SFZ8008T**  
**Date calculated: 21/04/2021 10:23 AM**

**Full Report**  
**Registration: SFZ8008T**  
**Printed: 21/04/2021 10:24 AM**

### Summary Information

---

#### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Min Seng Chong	Currency:	SGD
Claim Reference:	SFZ8008T	Date of Incident:	20/01/21
Estimated Repair Time:	8	Hire Car Start:	
Actual Repair Days:	7	Hire Car End:	

### Vehicle Details

---

#### Vehicle

Manufacturer:	BMW
Model:	7-SERIES F01/02
Sub Model:	740 LI
Model Sheet Number:	01 06 11
Registration:	SFZ8008T
VIN number:	WBAKB42020CY83652
Odometer:	146375

#### Model Specs

FROM 09/2010	INTER LIGHT AMBIENCE	AIR CON AUTO 4-ZONES	REAR SCREEN-SUNBAND
DVD CHANGER	DIP/FOLD MIRROR	SURROUND VIEW	NAVIG-SYST PROFESS
HI-FI SPEAKER SYSTEM	COMFORT ACCESS SYST	AUTO TAILGATE CONTR	SOFT CLOSE AUTOMATIC
DAKOTA LEATHER TRIM	LUMBAR SUPPORT	FRONT COMFORT SEATS	HEATED FRONT SEATS
HEATED REAR SEAT	SIDE ROLLER BLIND	REARVIEW CAMERA	NOBLE WOOD FINELINE
PARK DISTANCE CONT	SPORT S-WHEEL LEATH	AUTOMATIC 6-SPEED	INTEGRAL ACTIVE STRG
DYNAMIC DRIVE	TYRES 245/50 R18..W	WHEELS 8J X 18 ALU	ROOF MLDG VEH COLOUR
ELECTRIC SUNROOF	VERSION HOT COUNTRY	TWO COAT METALLIC	

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All   
Underbody



## Labour

Code	Description	Time Base 12 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
41 52 580	R + R RIGHT REAR DOOR		4.0	14.00
41 52 504	ADJUST R/R DOOR		2.0	7.00
41 52 501	RENEW R/R DOOR (REMOVED)		31.0	108.50
51 16 905)	R + R R/R DOOR ROLLER BLIND		3.0	10.50
41 35 111	RENEW R/R SIDE PANEL		200.0	700.00
	INCLUDES: R + R REAR SEAT, SEAT BACKREST, TAILGATE, REAR WINDOW, TAIL LAMP, BUMPER, BUMPER CARRIER, BUMPER GUIDE, SILL MOULDING, LUGGAGE COMPARTMENT TRIM, REAR SILL COVER STRIP, UPPER C-PILLAR TRIM AND REAR DOOR			
36 11 512	R + R R/R WHEEL/TYRE		6.0	21.00
36 11 500	TYRE PUNCTURE INITIALIZE DISPLAY		1.0	3.50
00 00 556	VEHICLE CHECK (BY VEHICLE DIAGNOSTIC SYSTEM)		3.0	10.50
66 53 515	CALIBRATE BACKUP CAMERA (AFTER VEHICLE TEST)		1.0	3.50
2583	REAR BUMPER COVER REPAIR		20.0*	70.00
	<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
	<b>Panel / Mechanical Labour</b>		<b>22.60</b>	<b>271.0</b>
	<b>Total of Labour</b>			<b>948.50</b>

## Paint

Paint Work

Code	Description - TWO COAT METALLIC	Time Basis 12 WU/h	
		WU	Price SGD
99 52 548	R/R DOOR PAINTING STAGE 2	19.0	66.50
99 21 611	R/R OUTER HANDLE PAINTING STAGE 2	2.0	7.00
99 36 529	R/RR SIDE PANEL PAINTING STAGE 3	28.0	98.00
99 69 549	REAR BUMPER PAINTING STAGE 3	26.0	91.00
99 51 538	RIGHT FRONT DOOR PAINTING STAGE 1	10.0	35.00
99 37 509	RIGHT SILL PAINTING STAGE 1	15.0	52.50
99 31 542	RIGHT A-PILLAR PAINTING STAGE 1	5.0	17.50
99 21 509	RIGHT B-PILLAR PAINTING STAGE 1	10.0	35.00
99 36 509	R/RR SIDE PANEL PAINTING STAGE 1	11.0	38.50
99 99 000	ADDITIONAL TIME FOR ONE MAIN WORK INCLUDES: MIX COLOUR AND SPRAY COLOUR SAMPLE	22.0	77.00

<b>Total Paint</b>	<b>Hrs</b>	<b>WU</b>	<b>Price SGD</b>
	<b>12.30</b>	<b>148.0</b>	<b>518.00</b>

### Material Cost - Paint

	<b>Price SGD</b>
New Part Painting	70.50
Repair Painting	83.49
Surface-/Blend Paint	127.44
Material-constant Metal	13.47
<b>Total</b>	<b>294.90</b>

## Spare Parts

Code	Description	Part Number	Part Source	prices as at 2021-04-19	
					Price SGD
3162	CLEANER R1 RR SCREEN	83 19 2 211 217	Original x NN		0.00
3172	LOWER R/SCREEN TRIM	51 31 7 184 569	Original /NEC-		78.00
3526	R/C-PILLAR REINF	41 21 7 275 599	Original x NN		0.00
1782	R/R DOOR	41 00 7 203 982	Original /PP		2,160.00
1866	R/R OUTER HANDLE	51 21 7 231 934	Original /SCR		720.00
3482	R/RR SIDE PANEL	41 21 7 204 488	Original /CRU		2,040.00
9552	R/R WHEEL	36 11 6 775 777	Original /SCR		1,170.00
3516	R/S/PANEL CLEANER R1	83 19 2 211 217	Original x		0.00
3512	R/S/PNL ADHESIVE K5A	83 19 2 158 654	Original x	} NN	0.00
3514	R/S/PNL ADHESIVE K5B	83 19 2 157 298	Original x		0.00
3508	R/SIDE PANEL REP KIT	USE SINGLE PARTS	Original x		
3524	R/SILL REINFORCEMENT	41 21 7 275 568	Original x		0.00
2020	R/SUN BLIND	51 35 9 168 846	Original /BT (A)		1,345.00
3160	REAR SCREEN BOND KIT	83 19 2 289 285	Original x	} NN	0.00
3164	REAR SCREEN BUFFER	51 31 2 996 980	Original x		0.00
3520	S/PANEL B/RIVET N3	83 19 0 301 421	Original x		0.00
3518	S/PNL STAMP RIVET N4	83 19 2 158 080	Original x		0.00
4193	SEAM SEALANT	83 42 2 409 985	Original x		0.00
3522	SIDE PANEL EMC SCREW	83 19 0 301 639	Original x		0.00
3171	UP/COVER REAR SCREEN	51 31 7 184 568	Original /NEC		78.00

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

<b>Savings</b>	0.00
<b>Subtotal</b>	<b>7,591.00</b>
<b>Total</b>	<b>7,591.00</b>

### Extras

Code	Description	Price SGD
1000	ALIGNMENT&BALANCING WHEEL	60.00*
1001	BODY SEALANT REAR FENDER RH	30.00*
1002	SEALANT REAR WINDSCREEN	40.00*
<b>Total Extras</b>		<b>130.00</b>

### Final Calculation

	SGD	SGD
<b>Parts</b>	7,591.00	
<b>Total Parts</b>		<b>7,591.00</b>
<b>Labour Time Base 12 WU/h</b> Total 271.0 WU X 42.00 SGD/h	948.50	
<b>Total of Labour</b>		<b>948.50</b>
<b>Total Of Extras</b>		<b>130.00</b>
<b>Paint Work Time Base 12 WU/h</b> Labour Cost 148.0 WU X 42.00 SGD/h Material Cost	518.00 294.90	
<b>Total Paint Including Material</b>		<b>812.90</b>
<b>Repair Cost Excludes GST</b>		<b>9,482.40</b>
GST (+7.00%)		663.77
<b>Repair Cost Included GST</b>		<b>10,146.17</b>
<b>Deductions (Excludes GST)</b> Deduction For Excess	-1,500.00	
<b>Total Of Deductions (Excludes GST)</b>		<b>-1,500.00</b>
<b>Grand Total Excludes GST</b>		<b>7,982.40</b>
GST (+7.00%)		558.77
<b>Grand Total Included GST</b>		<b>8,541.17</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

9,482.40  
- 20%  
7,582.92

### Comments

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

LIS  
 \$6,000 (before Excess)  
 7days

### Assessment Note

No assessment notes entered.