

Section A - Accident Details

Registration Number	SHB5105T
Case Reference Number	TAX/01/21/2064
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	PHUA TECK THUAN
Type of Accident	Head to Rear
Accident Date and Time	29/1/2021 9:25 AM
Accident Reported Date and Time	29/1/2021 1:54 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109617
Special Instruction to ARC, if any	REAR LEFT PORTION / CHINA TAIPING - LKK
Prepared Date and Time	30/1/2021 9:09 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$300.00
Total Spray Cost	\$2,266.00	\$600.00
Total Spare Part Cost	\$6,719.03	\$1,797.98
Total Other Cost	\$730.00	\$220.00
TOTAL COST	\$10,391.03	\$2,917.98
Lump Sum Total	\$10,400.00	\$2,900.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / China Taiping
ARC / Surveyor Sign Off Date	02/02/2021 5:14 PM	02/02/2021 4:03 PM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 1 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2102-0262	Invoice Number	
Quotation Date	18.02.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$676.00	\$300.00
Total Labour	\$676.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$100.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR FENDER LOWER PANEL LH	\$250.00	\$200.00
Total Spray Painting & Panel Beating	\$2,266.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPAIR REAR FENDER LOWER PANEL LH	\$250.00	\$200.00
Total Other Costs	\$730.00	\$220.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace
		5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given

Nec
SVC
BR
SVC
SVC
SVC
SVC
CR4
SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore	
FAX Number	63685592
Estimator Telephone Number	68662623
Accident Reporting Number	68662672

Date Generated : 18/02/2021

User ID : PohSuan

5256647900	FILLER, RR BUMPER , LH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	R
5216947020	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X Svc
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	Nec
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X Svc
8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X Svc
8156147151	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$438.10	0.00	\$0.00	Replace	Check	X Svc
8159147010	LENS & BODY ASSY , RR BUMPER , LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	CR4
8149847020	COVER, REAR COMBINATION LAMP, LH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X Svc
5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X Svc
5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X Svc
6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X Svc
5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	CR4
5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X Svc
5246247030	PAD, RR BUMPER, RH & LH , 1	1.00	\$3.80	25.00	\$2.85	Replace	Replace	Nec
5246247020	PAD, RR BUMPER, RH & LH , 2	1.00	\$3.80	25.00	\$2.85	Replace	Replace	Nec
5246247010	PAD, RR BUMPER, RH & LH , 3	1.00	\$3.80	25.00	\$2.85	Replace	Replace	Nec
6160247160	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X Svc
6556547010	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$33.70	0.00	\$0.00	Replace	Not Given	X Svc
6563847060	LINER, REAR FENDER , LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X Svc
6294047010	DUCT ASSY, QUARTER VENT , RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X Svc
4261147450	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X Svc 2247.47
4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X Svc
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X Svc 20%
6163247900	PANEL, QUARTER WHEEL HOUSE , OUTER LH	0.00	\$286.80	0.00	\$0.00	Replace	Not Given	X Svc
7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	R
7544147090	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	Nec 1797.98
7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	Nec 300.00
7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$52.30	0.00	\$0.00	Replace	Not Given	X Svc 820.00
7540348010	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	Nec
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	Nec
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	Nec 2917.95
5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X Svc
5831147130	SPARE TYRE PANEL , PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Not Given	X Svc
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X Svc 45 \$2924
Total			\$9,808.44		\$1,534.50			4days

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
5256647900			FILLER, RR BUMPER , LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
8156147151			LENS & BODY, REAR COMBINATION LAMP , LH	1.00	\$438.10	10.00	\$394.29	Replace	Replace
6294047010			DUCT ASSY, QUARTER VENT , RH & LH	1.00	\$65.00	25.00	\$48.75	Replace	Replace
Total					803.00		712.97		