

ASS. REC. BY: Marcus

REF:

CS/CT1 21001803/49d3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 02/3 12/13/14

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

MER-TP

5840

24/2/24 P/P \$5840.00 confirmed with Renamer (lead \$6146, 51%)

LTA 24826 CN4 12-2-24



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Polymedic Trading Enterprise Pt
	Reg No/Reg Date	GT1565S / 28/01/2015
	Date In/Mileage	05/02/2021/ 107713
	Chassis No	VF77F9HF8EJ794117
	Engine No	10JBFR0014738
	Make/Model	CITCV/BERLINGO L2 1.6 ETG PANEL
	Colour/Trim	ZRM / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	05/02/2021/ 12:07	DS	303 / Renemer	61254			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON RH ACCIDENT AFFECTED AREAS						100.00
S	MIPNT88088	TO TRANSFER RHF & RH SLIDING DOOR COMPONENTS & MECHANISM						1280.00
S	MIPNT88088	TO REPLACE RHF FENDER,RH SIDE MIRROR,RHF DOOR,RH SLIDING DOOR,ETC						3200.00
		TO REPAIR RHF A PILLAR						
		STRAIGHTEN,REFORM,ALIGN ON RH ACCIDENT AFFECTED AREAS						
S	MIPNT98088	SPRAY PAINTING ON RH ACCIDENT AFFECTED AREAS						2200.00
S	MIPNT88088	COMPANY REGISTRATION STICKER						50.00
S	MIPNT88088	COMPANY STICKER (POLYMEDIC)						150.00
M	C7841Y2	RH FRONT WING			1.00	619.00	0.00	619.00
M	C9015EL	RH DOOR TRIM CHEATER			1.00	151.00	0.00	151.00
M	C1611912680	RH FRONT MUDGUARD			1.00	157.00	0.00	157.00
P	C1609267280	RIVET,WHEEL GUARD			10.00	1.00	0.00	10.00
M	C96777550XT	RH REAR VIEW MIRROR			1.00	356.00	0.00	356.00
M	C1608751180	RH COVER REAR VIEW M			1.00	24.00	0.00	24.00
M	C9015EF	RH DOOR INT GUSSET D			1.00	20.00	0.00	20.00
M	C9004Z6	RH FRONT DOOR			1.00	1201.00	0.00	1201.00
M	C8545GT	RH DOOR PROTECTOR			1.00	97.00	0.00	97.00
M	C9202R6	RH FIXED WINDOW			1.00	239.00	0.00	239.00
M	C9300W1	RH WINDOW CHANNEL			1.00	211.00	0.00	211.00
M	C9101GE	RH DOOR HANDLE			1.00	110.00	0.00	110.00
M	C9008S2	SIDE DOOR RH			1.00	1280.00	0.00	1280.00
M	C8546X1	RH PROTECTOR SLIDING			1.00	96.00	0.00	96.00
M	C9101GG	RH HANDLE SLIDING DO			1.00	110.00	0.00	110.00
M	C5416K4	WHEEL CAP			1.00	75.00	0.00	75.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Polymedic Trading Enterprise Pt
	Reg No/Reg Date	GT1565S / 28/01/2015
	Date In/Mileage	05/02/2021/ 107713
	Chassis No	VF77F9HF8EJ794117
	Engine No	10JBFR0014738
	Make/Model	CITCV/BERLINGO L2 1.6 ETG PANEL
	Colour/Trim	ZRM / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	05/02/2021/ 12:07	DS	303 / Renemer	61254

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
<p>Z NOTES ACCIDENT ON 04/02/2021 ALONG CAUSEWAY POINT LOADING BAY OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: GBD8045Z TP INS: CHINA TAIPING</p> <p style="text-align: center; font-size: 48px; opacity: 0.5;">Estimate</p> <div style="border: 1px solid black; padding: 5px; margin: 10px auto; width: 80%;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				

Confirm & accepted by

Parts	4,756.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,230.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	11,986.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



CITROËN

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Polymedic Trading Enterprise Pt</td></tr> <tr> <td>Reg No/Reg Date</td><td>GT1565S / 28/01/2015</td></tr> <tr> <td>Date In/Mileage</td><td>05/02/2021/ 107713</td></tr> <tr> <td>Chassis No</td><td>VF77F9HF8EJ794117</td></tr> <tr> <td>Engine No</td><td>10JBF80014738</td></tr> <tr> <td>Make/Model</td><td>CITCV/BERLINGO L2 1.6 ETG PANEL</td></tr> <tr> <td>Colour/Trim</td><td>ZRM / BK</td></tr> </table>	Cust No/Name	/Polymedic Trading Enterprise Pt	Reg No/Reg Date	GT1565S / 28/01/2015	Date In/Mileage	05/02/2021/ 107713	Chassis No	VF77F9HF8EJ794117	Engine No	10JBF80014738	Make/Model	CITCV/BERLINGO L2 1.6 ETG PANEL	Colour/Trim	ZRM / BK
Cust No/Name	/Polymedic Trading Enterprise Pt														
Reg No/Reg Date	GT1565S / 28/01/2015														
Date In/Mileage	05/02/2021/ 107713														
Chassis No	VF77F9HF8EJ794117														
Engine No	10JBF80014738														
Make/Model	CITCV/BERLINGO L2 1.6 ETG PANEL														
Colour/Trim	ZRM / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	22/02/2021/ 11:35	DS	303 / Renemer	61254

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC/SCANNING				250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON RH ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088 TO REPLACE RHF FENDER,RH SIDE MIRROR,DOOR HANDLE,ETC TO REPAIR RHF A PILLAR,RHF DOOR,RH SLIDING DOOR STRAIGHTEN,REFORM,ALIGN ON RH ACCIDENT AFFECTED AREAS				1920.00
S MIPNT98088 SPRAY PAINTING ON RH ACCIDENT AFFECTED AREAS (RHF FENDER,RHF A PILLAR,RHF DOOR,RH SLIDING DOOR)				2000.00
S MIPNT88088 COMPANY REGISTRATION STICKER				50.00
S MIPNT88088 COMPANY STICKER (POLYMEDIC)				150.00
X C7841Y2 RH FRONT WING	1.00	619.00	0.00	619.00
X C9015EL RH DOOR TRIM CHEATER	1.00	151.00	0.00	151.00
X C96777550XT RH REAR VIEW MIRROR	1.00	356.00	0.00	356.00
X C1608751180 RH COVER REAR VIEW M	1.00	24.00	0.00	24.00
M C9015EF RH DOOR INT GUSSET D	1.00	20.00	0.00	20.00
X C9101GE RH DOOR HANDLE	1.00	110.00	0.00	110.00
X C9101GG RH HANDLE SLIDING DO	1.00	110.00	0.00	110.00
Z NOTES ACCIDENT ON 04/02/2021 ALONG CAUSEWAY POINT LOADING BAY OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP#: GBD8045Z TP INS: CHINA TAIPING				
Z NOTES FINALIZATION (TOTAL 6 WORKING DAYS) ATTENTION TO: MR. MARCUS CHUA				

Confirm & accepted by	Parts	1,390.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	4,450.00
	Others(Lub,etc)	0.00
	Sundry	0.00
Authorized signatory and company stamp	Total(w/o GST)	5,840.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.