

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001803/UQD3Q2
Date: 05/03/2021

REFERENCE

| | | | |
|-----------------------|---|----------------------|-------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNW00037962001 |
| Claimant Vehicle No : | GT1565S | Insured Vehicle No : | GBD8045Z |
| Date of Loss: | 04/02/2021 | Nature of Claim: | TP |
| | | Claim No: | SNM21D200729/C02/THAMYL |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | GT1565S | Engine No: | 10JBFR0014738 |
| Make & Model: | CITROEN BERLINGO, 1.5 D BLUEHDI EAT8 (M) | Chassis No: | VF77F9HF8EJ794117 |
| Reg. Date: | 28/01/2015 (Man. Year: 2014) | Odometer: | 107713 km |
| Colour: | Silver | | |
| Engine Capacity: | 1560 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Michelin 5 mm | Rear Left Side: | Michelin 5 mm |
| Front Right Side: | Michelin 5 mm | Rear Right Side: | Michelin 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|-----------------|-----------------|--------------|
| Parts | 4,956.00 | 1,590.00 | 3,366.00 | 67.92 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,030.00 | 4,250.00 | 2,780.00 | 39.54 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 11,986.00 | 5,840.00 | 6,146.00 | 51.28 |
| + GST 7.00/7.00% (S\$) | 839.02 | 408.80 | 430.22 | 51.28 |
| Nett Amount (S\$) | 12,825.02 | 6,248.80 | 6,576.22 | 51.28 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 08/02/2021 | |
| Date Inspected: | 08/02/2021 | Inspected At: |
| Estimated Period of Repair: | 6.0 days | Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ) 330 Ubi Road 3 Singapore 408650 |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | (Last Synchronised: 03 Mar 2021) | |
| Parts: | N/A | CITROEN BERLINGO 1.5 D BLUEHDI EAT8 (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GT1565S) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------|--------------------------------|-------------|------------|
| 1 | 1 | | *RH FRONT WING | Badly Dented | 619.00 FS | *619.00 FS |
| 2 | 1 | | *RH DOOR TRIM CHEATER | Scratched | 151.00 FS | *151.00 FS |
| 3 | 1 | | *RH FRONT MUDGUARD | Not Necessary | 157.00 FS | *- FS |
| 4 | 10 | | *RIVET,WHEEL GUARD | Not Necessary | 10.00 FS | *- FS |
| 5 | 1 | | *RH REAR VIEW MIRROR | Broken | 356.00 FS | *356.00 FS |
| 6 | 1 | | *RH COVER REAR VIEW M | Cracked | 24.00 FS | *24.00 FS |
| 7 | 1 | | *RH DOOR INT GUSSET D | Necessary | 20.00 FS | *20.00 FS |
| 8 | 1 | | *RH FRONT DOOR | Repair | 1,201.00 FS | *- FS |
| 9 | 1 | | *RH DOOR PROTECTOR | Not Necessary | 97.00 FS | *- FS |
| 10 | 1 | | *RH FIXED WINDOW | Not Necessary | 239.00 FS | *- FS |
| 11 | 1 | | *RH WINDOW CHANNEL | Not Necessary | 211.00 FS | *- FS |
| 12 | 1 | | *RH DOOR HANDLE | Cut | 110.00 FS | *110.00 FS |
| 13 | 1 | | *SIDE DOOR RH | Repair | 1,280.00 FS | *- FS |
| 14 | 1 | | *RH PROTECTOR SLIDING | Not Necessary | 96.00 FS | *- FS |
| 15 | 1 | | *RH HANDLE SLIDING DO | Scratched | 110.00 FS | *110.00 FS |
| 16 | 1 | | *WHEEL CAP (CUT) | Not Consistent With The Impact | 75.00 FS | *- FS |
| 17 | 1 | | *COMPANY REGISTRATION STICKER | Necessary | 50.00 FS | *50.00 FS |
| 18 | 1 | | *COMPANY STICKER (POLYMEDIC) | Necessary | 150.00 FS | *150.00 FS |

F=Franchise part. S=SpcNett.

| | | |
|--------------------------|-----------------|-----------------|
| Total Parts (S\$) | 4,956.00 | 1,590.00 |
|--------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | DIAGNOSTIC/SCANNING | New | 250.00 | 250.00 |
| 2 | TO CHECK ALL LIGHTING/WIRING SYSTEM ON RH ACCIDENT AFFECTED AREAS | New | 100.00 | 80.00 |
| 3 | TO TRANSFER RHF & RH SLIDING DOOR COMPONENTS & MECHANISM | New | 1,280.00 | 0.00 |
| 4 | TO REPLACE RHF FENDER,RH SIDE MIRROR,RHF DOOR,RH SLIDING DOOR,ETC.TO REPAIR RHF A PILLAR.STRAIGHTEN,REFORM,ALIGN ON RH ACCIDENT AFFECTED AREAS | New | 3,200.00 | 1,920.00 |
| 5 | SPRAY PAINTING ON RH ACCIDENT AFFECTED AREAS | New | 2,200.00 | 2,000.00 |
| Gross Labour Cost (\$\$) | | | 7,030.00 | 4,250.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >