

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 5-Feb-21
 MODEL: TOYOTA PRIUS
 VEHICLE NO.: SHA2666R
 INSURANCE: Longec

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR TRUNK LID COVER <i>Dented/Bt PHAs</i>	1	\$1,126.60	\$1,126.60	✓
REAR TRUNK LID LOCK <i>Bt / Dam</i>	1	\$457.90	\$457.90	✓
REAR TRUNK LID COVER TRIM BOARD <i>HH</i>	1	\$254.40	\$254.40	X
Boot Lid Trimboard, Centre <i>HH</i>	1	\$159.60	\$ 159.60	X
Boot Lid Trimboard SIDE (LH) <i>HH</i>	1	\$92.50	\$ 92.50	X
Boot Lid Trimboard REAR <i>HH</i>	1	\$124.80	\$ 124.80	X
BOOT HANDLE <i>HH</i>	1	\$31.80	\$31.80	X
REAR TRUNK LID RUBBER <i>damaged</i>	1	\$365.20	\$365.20	✓
REAR TRUNK LID GLASS (BLACK COLOR) <i>Shattered</i>	1	\$969.70	\$969.70	✓
BOARD ASSY, BACK DOOR TRIM <i>crack / broken HH</i>	1	\$354.40	\$354.40	X
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>crack / broken</i>	1	\$896.30	\$896.30	✓
REAR TRUNK LID LOGO (PRIUS) <i>Hec</i>	1	\$60.80	\$60.80	✓
REAR TRUNK LID LOGO (HYBRID) <i>Hec</i>	1	\$52.40	\$52.40	✓
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Hec</i>	1	\$52.90	\$52.90	✓
REAR TRUNK LID STRIKER <i>damaged</i>	1	\$98.70	\$98.70	X
SPOILERSUB-ASSY, REAR <i>crack / broken</i>	1	\$953.70	\$953.70	✓
REAR BUMPER <i>crack / distorted</i>	1	\$458.60	\$458.60	✓
REAR BUMPER RE-INFORCEMENT <i>Bt / Dented</i>	1	\$318.80	\$318.80	✓
REAR BUMPER LOWER COVER <i>damaged</i>	1	\$552.60	\$552.60	✓
REAR BUMPER SIDE RETAINER <i>SVZ</i>	1	\$112.70	\$112.70	X
REAR BUMPER TOWING COVER <i>HH</i>	1	\$82.70	\$82.70	X
REAR BUMPER CLIPS <i>Hec</i>	1	\$22.00	\$22.00	✓
REAR BUMPER SIDE CLIP <i>HH</i>	1	\$25.00	\$25.00	X
REAR BUMPER UPPER STOPPER (LH) <i>HH</i>	2	\$76.40	\$152.80	X
SEAL, REAR BUMPER SIDE, LH <i>HH</i>	1	\$148.40	\$148.40	X
REAR BUMPER UNDER SIDE COVER (LH) <i>HH</i>	1	\$232.00	\$232.00	X
ARM SUB-ASSY, REAR BUMPER, (LH) <i>mostly crack</i>	1	\$139.60	\$139.60	✓
TAIL LAMP ASSY (UPPER) <i>H/S broken</i>	1	\$557.90	\$557.90	✓
TAIL LAMP ASSY (LOWER) <i>H/S broken</i>	1	\$548.40	\$548.40	✓
TAIL LAMP QUARTER PANEL <i>Dented</i>	1	\$216.00	\$216.00	✓
TAIL LAMP SIDE COVER <i>H/S end / distorted</i>	1	\$256.00	\$256.00	✓
REAR TAILLAMP GUIDE - WHITE <i>HH</i>	1	\$95.30	\$95.30	X
REAR END PANEL <i>Dented</i>	1	\$602.10	\$602.10	✓
REAR END PANEL GARNISH <i>damaged</i>	1	\$165.80	\$165.80	✓
REAR WIRING ASSY <i>HH</i>	1	\$582.40	\$582.40	X
REAR SPARE TYRE PANEL <i>HH</i>	1	\$667.70	\$667.70	X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>HH</i>	1	\$101.40	\$101.40	X
REAR FIBER TOOL BOX TRIM (LH) <i>HH</i>	1	\$598.00	\$598.00	X
REAR FIBER TOOL BOX CENTER <i>HH</i>	1	\$186.20	\$186.20	X
SPARE TYRE LOCK NUT <i>HH</i>	1	\$88.40	\$88.40	X
SPARE TYRE LOCK NUT BRACKET <i>HH</i>	1	\$113.50	\$113.50	X

SPARE TYRE SIDE PANEL (LH) <i>HH</i>	1	\$196.50	\$196.50	X
REAR EXHAUST PIPE <i>HH</i>	1	\$1,163.40	\$1,163.40	X
REAR EXHAUST PIPE HANGER <i>HH</i>	1	\$40.70	\$40.70	X
REAR EXHAUST PIPE INSULATOR <i>HH</i>	1	\$314.60	\$314.60	X
SUB TOTAL			\$14,791.20	
LESS 20% 25%			\$2,958.24	
DISCOUNTED TOTAL			\$11,832.96	
REVERSE CAMERA ASSY <i>HH</i> SN	1	\$380.00	\$380.00	X
REAR TRUNK LOWER W/S MOULDING <i>Hec</i> SN	1	\$180.00	\$180.00	✓
REAR LOWER W/S SEALANT <i>Hec</i> SN	1	\$46.00	\$46.00	✓
REAR WINDSCREEN MOULDING <i>Hec</i> SN	1	\$160.00	\$160.00	✓
REAR WINDSCREEN SEALANT <i>Hec</i> SN	1	\$46.00	\$46.00	✓
REAR TRUNK LID APPS STICKER <i>Hec</i> SN	1	\$40.00	\$40.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>Hec</i> SN	1	\$60.00	\$60.00	✓
REAR BUMPER REVERSE SENSOR <i>Dem</i> SN	1	\$135.70	\$135.70	✓
SUB TOTAL			\$1,047.70	
Labour Charge				
Panel Beating	1	\$1,800.00	\$1,800.00	900/-
Spray Painting Charge	1	\$1,400.00	\$1,400.00	800/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$100.00	\$100.00	40/-
Towing Charge	1	\$80.00	\$80.00	HH
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00	80/-
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	40/-
Remove/Refix Fuel Tank	1	\$80.00	\$80.00	HH
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	HH
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	HH
TOTAL LABOUR			\$4,550.00	
ESTIMATE TOTAL			\$17,430.66	
will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

8773.30

6579.97

667.70

1890.00

9137.67

457300/-

08/02/2021 @ 1000hrs

HA Auction

2/sum 5 days.

1 Jan

2kk Auto

[Signature]

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: