

# SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E  
 8 Kaki Bukit Avenue 4  
 #08-09 Premier @ Kaki Bukit  
 Singapore 415875  
 Tel: 6341 6789 Fax: 6341 6778  
 Email: smartoneauto@gmail.com

# SMART



ENR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- DATE: 16.02.21 must be resurveyed and is subject to final approval from Insurance Company

Signature:  
Date:

xiao chan.

TO : **CHINATAIPING** MOTOR CLAIMS DEPTS. Sdged by Repairer  
 VEHICLE NO : **SLX5071T**  
 MODEL : **MERCEDES BENZ GLA180**  
 DATE OF ACCIDENT : 05.02.21  
 TIME OF ACCIDENT : 11:45HRS

WDC1569422J488065

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER (UPPER) <i>Deboned</i>	1	\$ 1,691.00	\$ 1,691.00
2	FRONT BUMPER SIDE ( LOWER) LH <i>lt</i>	1	\$ 145.00	\$ 145.00
3	FRONT BUMPER SIDE GRILLE GARNISH LH <i>new</i>	1	\$ 95.00	\$ 95.00
4	FRONT BUMPER LOWER GRILLE C/W CHROME <i>new</i>	1	\$ 396.00	\$ 396.00
5	FRONT BUMPER BOTTOM GARNISH <i>new</i>	1	\$ 380.00	\$ 380.00
6	FRONT BUMPER SENSOR LH <i>Dangd</i>	2	\$ 228.00	\$ 456.00
7	FRONT BUMPER SENSOR HOLDER <i>LH new</i>	4	\$ 65.00	\$ 260.00
8	FRONT BUMPER SIDE RETAINER <i>LH new</i>	2	\$ 148.00	\$ 296.00
9	FRONT BUMPER SPONGE <i>scrubd</i>	1	\$ 198.00	\$ 198.00
10	HEAD LAMP LH <i>crackd</i>	1	\$ 2,916.00	\$ 2,916.00
11	HEAD LAMP LOWER BRACKET LH <i>2nd</i>	1	\$ 98.00	\$ 98.00
12	HEAD LAMP SIDE BRACKET LH <i>1st</i>	1	\$ 85.00	\$ 85.00
13	FRONT FENDER LH <i>Dented</i>	1	\$ 1,102.00	\$ 1,102.00
14	FRONT FENDER ARCED GARNISH LH <i>lt</i>	1	\$ 277.00	\$ 277.00
15	FRONT FENDER COWLING RH (FRONT) <i>Dehd</i>	1	\$ 228.00	\$ 228.00
16	FRONT SUPPORT TOP PANEL <i>new</i>	1	\$ 940.00	\$ 940.00
17	FRONT WHEEL RIM LH <i>lt</i>	1	\$ 1,080.00	\$ 1,080.00
18	FRONT ABS SENSOR <i>new</i>	1	\$ 285.00	\$ 285.00
19	FRONT WHEEL HUP WITH BEARING LH <i>Dangd</i>	1	\$ 702.00	\$ 702.00
20	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 1,062.00	\$ 1,062.00
21	FRONT KNUCKLE ARM LH <i>new</i>	1	\$ 1,116.00	\$ 1,116.00
22	FRONT LOWER ARM LH <i>Best</i>	1	\$ 828.00	\$ 828.00
23	FRONT STABILIZER LINKAGE LH <i>new</i>	1	\$ 183.00	\$ 183.00

1381  
 ✓  
 x  
 x.  
 x  
 228.  
 45.  
 148.  
 ✓  
 2635  
 +  
 x  
 891.  
 ✓  
 x  
 80(s.w)  
 x.  
 ✓  
 x  
 ✓  
 705.  
 x.

7683  
 6914.70 S.N: 800

TOTAL PRICE \$ 14,819.00  
 LESS 10% \$ 1,481.90  
**SUB TOTAL PRICE \$ 13,337.10**

TO : CHINATAIPING MOTOR CLAIMS DEPTS  
 VEHICLE NO : SLX5071T  
 MODEL : MERCEDES BENZ GLA180  
 DATE OF ACCIDENT : 05.02.21  
 TIME OF ACCIDENT : 11:45HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 120.00	\$ 120.00 <i>30</i>
2	FRONT BUMPER BOTTOM GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00 <i>x</i>
3	FRONT BUMPER SIDE GRILLE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00 <i>x</i>
4	FRONT SUPPORT TOP PANEL SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00 <i>x</i>
5	FRONT FENDER COWLING CLIPS(SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
6	FRONT FENDER ARCED GARNISH CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
7	FRONT WHEEL TYRE LH <i>Not Neu</i>	1	\$ 780.00	\$ 780.00 <i>x 90</i>
8	BRAKE OIL <i>Not Neu</i>	1	\$ 60.00	\$ 60.00 <i>x</i>

TOTAL \$ 1,410.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>600</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	WIRING CHECK	\$ 150.00	<i>30</i>
4	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
5	REMOVE AND REPLACE FRONT BUMPER SENSOR	\$ 120.00	<i>50</i>
6	REMOVE AND REFIX FRONT STEERING RACK AND PINION	\$ 350.00	<i>x</i>
7	SPECIAL COATING	\$ 880.00	<i>400</i>
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	<i>180</i>
9	TO PRESS FRONT WHEEL BEARING	\$ 120.00	<i>x</i>
10	FOUR WHEEL ALIGNMNET	\$ 120.00	<i>80</i>
11	RESET ABS LIGHT	\$ 480.00	<i>x</i>
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 600.00	<i>x</i>

TOTAL \$7,130.00

TOTAL PARTS COST : \$ 14,747.10  
 TOTAL LABOUR COST : \$ 7,130.00  
 TOTAL REPAIR COST : \$ 21,877.10

*Adrian G oShop*  
*H/S 17/02/21*  
*total: 9744.7*

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
 PARTS PRICES ARE SUBJECT TO CHANGES.

*H/S: 7.8k*  
*(7.819)*