



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988

BUSINESS REG NO. 375654/00C

Vehicle No : 888 H807T	Accident Date : 4.2.2021
Mileage :	Make / Model : HONDA ODYSSEY
	CHASSIS : JHM RD18506C200063
Date :	Fax NO. : 6445 2934

Items			
1	Rear BootLid	1030.50 bt	\$1257.40
2	" BootLid damper x2 @ 155.30	Rp	\$310.60
3	" BootLid Lock	photo. bt	\$219.30
4	" BootLid weatherstrip	trm	\$151.60
5	" BootLid Camera	mx	\$280.
6	" BootLid trim board	del	\$212
7	" BootLid LH & RH Panel x2 @ 76.20 mx		\$152.40
8	" BootLid outer Panel	cm	\$406.10
9	" BootLid windscreen	cm	\$1203.50
10	" BootLid windscreen moulding	net	\$138.00
11	" BootLid Logo	net	\$37.40
12	" BootLid emblem	net	\$45.50
13	" BootLid trim board clip	net	\$38.00
14	" BootLid number Plate Lamp.	cm	\$62.10
15	" BootLid number Plate Lamp holder	cm	\$85.00
16	No. Plate & Casing	SN bt / 45	\$50.00
17	Rear Bumper	del	\$896.00
18	Rear Bumper side retainer x2 @ 22.20 Xmm		\$46.40
19	Rear Bumper side chrome x2 @ 65.30 cm		\$130.60
20	Rear Bumper reverse sensor 4 pc 250. mm		\$380.00
21	Rear Bumper Clip	net	\$38.00
22	Rear Bumper Beam	bt	\$268.40
23	Rear Bumper Bracket LH & RH @ 21.30 X 2		\$42.60
24	Rear BootLid wiper motor	bt	\$228.60
25	Rear BootLid wiper ARM	bw	\$46.00
26	Rear BootLid wiper rubber	mis	\$44.00
27	Rear BootLid ARM Cover	mis	\$12.90
28	Rear Bumper towing Cover	un. X	\$32.20



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988

BUSINESS REG NO. 375654/00C

Vehicle No : SGG 480T T	Accident Date : 4.2.2021
Mileage :	Make / Model : HONDA ODYSSEY
	CHASSIS : JHMRD18506C200062
Date :	Fax NO. : 64452934

Items			
1	Rear Taillamp LH	one ✓	\$ 385.60
2	Rear Taillamp RH	one ✓	\$ 385.60
3	Rear Fender LH	Rx	\$ 832.20
4	Rear Fender RH	Rx	\$ 832.20
5	Rear End panel	photo. bt ✓	\$ 545.90
6	Rear End panel Top Barish	photo. dt ✓	\$ 551.50
7	Rear Spare tyre panel	Rx	\$ 585.90
8	Rear Spare tyre Board	one ✓	\$ 354.10
9	Rear Spare tyre	nn x	\$ 280.00
10	Rear Spare tyre nut + bolt.	nn x	\$ 45.10
11	Rear Tailbrake Sealant	one SN60	\$ 120.
12	Rear RH Fender Barish inner	dt ✓?	\$ 485.60
13	Rear LH Fender Barish inner	dt ✓?	\$ 485.60
14	Rear RH Fender Barish clip	one ✓?	\$ 38.00
15	Rear LH Fender Barish clip	one ✓?	\$ 38.00
16	Rear Bootlid Third Brake Lip	one ✓	\$ 215.00 150
		8492	
		20% - 6793.60.	
		SN - 81105	



發 福 摩 哆 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

3

To straighten, repair, realign on effected area, and replace damaged parts, end panel.	#1400.00 1000.
To spray painting on affected area, (Bootlid, Rear Bumper, LH & RH Fender, Rear End panel, tyre panel).	#1600.00 1200.
To spray anti-rust coating on effcted panel.	#120.00 ^{40.}
To remove and re-install rear interior trims, Boards, Rarish etc necessary repair	#250.00 ^{60.}
To transfer tailgate, mechanism + component	#120.00 30.
To check rear electrical wiring system	#80.00 120.
To transfer rear windcreams to new tailgate	#150.00 60.
Remove & Fix rear sensor, Rear camera	#150.00 40
Rear end panel Sealant	#100.00 2610
Est to repair 10 days.	
Tayfth 97495779 7 days	16662
WP' 8/2/21 @ 545 pm	
2/3 Repair after repair	

Tayfth @ Thumpoon

6793
105
2610
9508
11587600, 07 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: