

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 6 Feb 2021

ASSESSMENT FOR REPAIR: HONDA CBR150R - FBR7180Z

Chassis No.:
 Engine No.:

Qty	Description	Estimate
2 pcs	• Steering stem bearing	\$90.00 ? X SVL / NEC
1 pc	• Front fork steering stem	\$295.00 ? X SVL
1 pc	Left tail cover amblem	\$40 \$65.00 / NEC
1 pc	Left tail cover	\$145.00 / SCR
1 pc	Left rear signal	\$125.00 / SCR
1 pc	Headlamp fairing	\$185.00 / SCR
1 pc	Headlamp fairing amblem	\$30 \$55.00 / NEC
1 pc	Left side front signal	\$125.00 / SCR
1 pc	Right side fairing amblem	\$30 \$55.00 / NEC
1 pc	Right side fairing	\$200 \$225.00 / SCR
1 pc	Left side fairing amblem	\$30 \$55.00 / SCR NEC
1 pc	Left side fairing	\$200 \$225.00 / SCR
1 pc	Left balancer	\$55.00 / BT
1 pc	Clutch lever	\$65.00 / SCR
1 pc	• Left steering handle	\$120 \$185.00 ? / BT
1 pc	Left rear footrest holder	\$155.00 ? X SVL
1 pc	Left rear footrest	\$75.00 ? / SCR
1 pc	Left view mirror	\$115.00 / JCR
1 pc	Gear pedal assy	\$95.00 ? / BT X SVL
1 pc	• Left front footrest	\$75.00 ? / SCR
1 pc	• Left front footrest holder	\$130 \$175.00 ? / BT
1 pc	• IU bracket	\$45.00 ? / BT
		1,880.00 \$2,685.00
	Less discount 10%	\$268.50
		\$2,416.50
	Special nett items	\$157.00
1 pc	ERP IU	\$30.00 / EXTRA 2ED
1)	Towing charges	\$100.00 ✓
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00 ✓ 300
3)	To balance front and rear wheel rims	\$60.00 ✓ X NN
4)	To knock, straighten chassis & body balancing	\$380.00 ✓ X NN
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$150.00 ? X NN
6)	Spray painting	\$400.00 200
	Total Estimate	500.00 <u>\$4,236.50</u>

Note: The above estimate is subjected to the prevailing GST of 7%

Nm2 CLK
9/2/2021 1330
LIS
3 DAYS

CHECK ITEM PHOTOS
AFTER REPAIR PHOTOS



For Bike Production Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- **Parts prices** are subject to confirmation
- **Third party survey** is on a "Without Prejudice" basis
- No **illegal modification(s)** is allowed
- **Supplementary item(s)** must be resurveyed and is subject to **final approval from Insurance Company**

Acknowledged by Repairer

Signature:

Date:

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 24 Feb 2021

ASSESSMENT FOR REPAIR: HONDA CBR150R - FBR7180Z

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left switch assy	\$130 \$205.00 ✓ DEF
1 pc	Left black fairing inner cover	\$150 \$185.00 ✓ ERK
1 pc	Left side fairing grey cover	\$165.00 ✓ DEF
1 pc	Headlamp inner cover	\$145.00 ✓ DEF
1 pc	Left upper front cover	\$75.00 ✓ DEF
1 pc	Left side cover lower	\$78.00 ✓ DEF
		<hr/>
		743 \$853.00
	Less discount 10%	\$85.30
		<hr/>
		\$767.70
		<hr/>
	<u>Special nett items</u>	
1)	Labour for supplemenatry items	\$150.00 50
		<hr/>
	Total Estimate	<u><u>\$917.70</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

PARTS \$2,623.00
 LESS 10% \$2,360.70
 NETT \$ 157.00
 LABOUR \$ 550.00
 \$3,067.70
 LESS L/S 20% \$2,454.16
\$2,450.00 / 3 REPAIR DAYS


 For Bike Production Pte Ltd