

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 6 Feb 2021

ASSESSMENT FOR REPAIR: HONDA CBR150R - FBR7180Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
2 pc	• Steering stem bearing	\$90.00 ? X SVL / NEC
1 pc	• Front fork steering stem	\$295.00 ? X SVL
1 pc	Left tail cover amblem	\$65.00 / NEC
1 pc	Left tail cover	\$145.00 / SCR
1 pc	Left rear signal	\$125.00 / SCR
1 pc	Headlamp fairing	\$185.00 / SCR
1 pc	Headlamp fairing amblem	\$55.00 / NEC
1 pc	Left side front signal	\$125.00 / SCR
1 pc	Right side fairing amblem	\$55.00 / NEC
1 pc	Right side fairing	\$225.00 / SCR
1 pc	Left side fairing amblem	\$55.00 / SCR NEC
1 pc	Left side fairing	\$225.00 / SCR
1 pc	Left balancer	\$55.00 / BT
1 pc	Clutch lever	\$65.00 / SCR
1 pc	• Left steering handle	\$185.00 ? / BT
1 pc	Left rear footrest holder	\$155.00 ? X SVL
1 pc	Left rear footrest	\$75.00 ? / SCR
1 pc	Left view mirror	\$115.00 / JCR
1 pc	Gear pedal assy	\$95.00 ? / BT X SVL
1 pc	• Left front footrest	\$75.00 ? / SCR
1 pc	• Left front footrest holder	\$175.00 ? / BT
1 pc	• IU bracket	\$45.00 ? / BT
		<hr/>
	Less discount 10%	\$2,685.00
		\$268.50
		<hr/>
		\$2,416.50
	<u>Special nett items</u>	
1 pc	ERP IU	\$157.00
		\$30.00 / EXTRA 2ED
1)	Towing charges	\$100.00 X
	Replace, realign and adjust above damaged parts, check wiring and lighting system	
2)	To balance front and rear wheel rims	\$700.00 300
3)	To knock, straighten chassis & body balancing	\$60.00 X NN
4)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$380.00 X NN
5)	Spray painting	\$150.00 ? X NN
6)		\$400.00 200
	Total Estimate	<hr/> <hr/>
		\$4,236.50

Note: The above estimate is subjected to the prevailing GST of 7%


Nm2 LKK
9/2/2021 1330

LIS

3 DAYS

CHECK ITEM PHOTO

AFTER REPAIR PHOTO



For Bike Production Pte Ltd