

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 6 Feb 2021

ASSESSMENT FOR REPAIR: HONDA CBR150R - FBR7180Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
2 pcs	Steering stem bearing	\$90.00
1 pc	Front fork steering stem	\$295.00
1 pc	Left tail cover amblem	\$65.00
1 pc	Left tail cover	\$145.00
1 pc	Left rear signal	\$125.00
1 pc	Headlamp fairing	\$185.00
1 pc	Headlamp fairing amblem	\$55.00
1 pc	Left side front signal	\$125.00
1 pc	Right side fairing amblem	\$55.00
1 pc	Right side fairing	\$225.00
1 pc	Left side fairing amblem	\$55.00
1 pc	Left side fairing	\$225.00
1 pc	Left balancer	\$55.00
1 pc	Clutch lever	\$65.00
1 pc	Left steering handle	\$185.00
1 pc	Left rear footrest holder	\$155.00
1 pc	Left rear footrest	\$75.00
1 pc	Left view mirror	\$115.00
1 pc	Gear pedal assy	\$95.00
1 pc	Left front footrest	\$75.00
1 pc	Left front footrest holder	\$175.00
1 pc	IU bracket	\$45.00
		<hr/>
		\$2,685.00
	Less discount 10%	\$268.50
		<hr/>
		\$2,416.50
	<u>Special nett items</u>	
1 pc	ERP IU	\$30.00
1)	Towing charges	\$100.00
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00
3)	To balance front and rear wheel rims	\$60.00
4)	To knock, straighten chassis & body balancing	\$380.00
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$150.00
6)	Spray painting	\$400.00
	Total Estimate	<hr/> <hr/>
		\$4,236.50

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 6 Feb 2021

ASSESSMENT FOR REPAIR: HONDA CBR150R - FBR7180Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
2 pcs	Steering stem bearing	\$90.00
1 pc	Front fork steering stem	\$295.00
1 pc	Left tail cover amblem	\$65.00
1 pc	Left tail cover	\$145.00
1 pc	Left rear signal	\$125.00
1 pc	Headlamp fairing	\$185.00
1 pc	Headlamp fairing amblem	\$55.00
1 pc	Left side front signal	\$125.00
1 pc	Right side fairing amblem	\$55.00
1 pc	Right side fairing	\$225.00
1 pc	Left side fairing amblem	\$55.00
1 pc	Left side fairing	\$225.00
1 pc	Left balancer	\$55.00
1 pc	Clutch lever	\$65.00
1 pc	Left steering handle	\$185.00
1 pc	Left rear footrest holder	\$155.00
1 pc	Left rear footrest	\$75.00
1 pc	Left view mirror	\$115.00
1 pc	Gear pedal assy	\$95.00
1 pc	Left front footrest	\$75.00
1 pc	Left front footrest holder	\$175.00
1 pc	IU bracket	\$45.00
		<hr/>
		\$2,685.00
	Less discount 10%	\$268.50
		<hr/>
		\$2,416.50
	<u>Special nett items</u>	
1 pc	ERP IU	\$30.00
1)	Towing charges	\$100.00
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$700.00
3)	To balance front and rear wheel rims	\$60.00
4)	To knock, straighten chassis & body balancing	\$380.00
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$150.00
6)	Spray painting	\$400.00
	Total Estimate	<hr/> <hr/>
		\$4,236.50

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd