



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHONG WOEI SONG  BLK 388 BUKIT BATOK WEST AVENUE #05-368 SINGAPORE 650388  Contact No Mobile: 91856895	Cust No/Name /CHONG WOEI SONG Reg No/Reg Date SMH9933C / 21/01/201 Date In/Mileage / 0 Chassis No KNAF1416MK5027078 Engine No G4FGJH715710 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	08/02/2021/ 10:09	BLC	442 / CocoLu	28683

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER				400.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				350.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY Sundry				20.00
M SUNDRY SUPPLY FRT NUMBER PLATE WITH FRAME				50.00
M COVER-FR BUMPER / CRU	1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER / CWT	1.00	262.00	00.00	262.00
M LAMP ASSY-DAY RUNNING LIGHT, LH	1.00	203.00	00.00	203.00
M MOULDING-FRONT BUMPER, LH / CWT	1.00	36.00	00.00	36.00
M LAMP ASSY-SIDE REPEATER, LH	1.00	143.00	00.00	143.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	00.00	84.00
M AIR DUCT-FR BUMPER, LH	1.00	14.00	00.00	14.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	00.00	22.00
M GRILLE ASSY-RADIATOR / CWT	1.00	223.00	00.00	223.00
M ORNAMENT-KIA NO.115 / MC	1.00	32.00	00.00	32.00
M BEAM COMPLETE-FR BUMPER	1.00	497.00	00.00	497.00
M CARRIER ASSY-FRONT END MODULE X	1.00	675.00	00.00	675.00

# Estimate

Stew (LKK) 8/2/21, 10-45am

00-NH ANL  
EXC - ?

P/P

By Ref Spg

3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting

Confirm &amp; accepted by: confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on **3,794.00** **265.58**  
**Nett 3,794.00**  
**Total Payable 4,059.58**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.