

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21001819/UTF3Q2

Date: 31/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00011752000

Claimant Vehicle No : FBG3012K **Insured Vehicle No :** PA5827D

Date of Loss: 28/01/2021 Nature of Claim: TP Claim No: SNM21D200568/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBG3012K**
 Make & Model: YAMAHA YBR125, 123cc (M) Engine No: E3J2E004456
 Reg. Date: 08/06/2012 (Man. Year: 2012) Chassis No: LBPKE1789C0001555
 Colour: Blue Odometer: 45481 km
 Engine Capacity: 124 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.73-18 Rear Tyre Size: 3.00-18
 Front Left Side: Timsun 6 mm Rear Left Side: Timsun 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	754.00	551.60	202.40	26.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	770.00	615.00	155.00	20.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,524.00	1,166.60	357.40	23.45
Approved Total (Overridden) (\$\$)		900.00		
(\$\$)	1,524.00	900.00	624.00	40.94
+ GST 7.00/7.00% (\$\$)	106.68	63.00	43.68	40.94
Nett Amount (\$\$)	1,630.68	963.00	667.68	40.94

INSPECTION

Date of Assignment: 19/03/2021

Date Inspected: 08/02/2021 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
 No. 6 Defu Lane 4
 Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Mar 2021)	
Parts:	N/A	YAMAHA YBR125 123cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBG3012K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BAN HANDLE	Bent	69.00 F	*69.00 FL
2	1		*COVER SIDE RH (WHITE)	Cut	98.00 F	*98.00 FL
3	1		*FOOTREST FRONT	Torn	42.00 F	*42.00 FL
4	1		*FORK FRONT ASSY RH	Repair	138.00 F	*- FL
5	1		*HEADLAMP ASSY	Cut	147.00 F	*147.00 FL
6	2		*HOLDER NUMBER PLATE	Necessary	5.00 F	*5.00 FL
7	1		*LAMP SIGNAL FRONT RH	Broken	54.00 F	*54.00 FL
8	1		*LEVER BRAKE	Scratched	19.00 F	*19.00 FL
9	1		*PLATE NUMBER FRONT (CURVED)	Bent	22.00 FS	*10.00 FS
10	1		*PROTECTOR MUFFLER (REAR)	Scratched	32.00 F	*32.00 FL
11	1		*RUBBER FOOTREST FRONT	Torn	28.00 F	*28.00 FL
12	1		*STICKER (SPEED POST) BOX REAR	Necessary	70.00 FS	*70.00 FS
13	1		*VISOR	Cracked	30.00 F	*30.00 FL
					Sub Total (\$\$)	754.00 604.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 52.40
					Total Parts (\$\$)	754.00 551.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	315.00	220.00
2	SPRAY PAINT ON COVER SIDE RH	New	42.00	35.00
3	SPRAY PAINT ON COVER TANK RH	New	28.00	25.00
4	SPRAY PAINT ON FRONT COWLING	New	65.00	50.00
5	SPRAY PAINT ON REAR FIBER BOX	New	210.00	200.00
6	SPRAY PAINTING ON COVER TAIL RH	New	65.00	50.00
7	TRANSPORT CHARGES	New	45.00	35.00
Gross Labour Cost (\$)			770.00	615.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >