



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
 PANDAN GARDENS CUSTOMER SERVICE CENTRE  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Abdul Jalil Bin Mohamad Reg No/Reg Date SFZ7767S / 12/02/201 Date In/Mileage / 0 Chassis No GF7W0401119 Engine No 4J11XK6012 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/02/2021/ 09:49	QUD	247 / DonBong	62784

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON LH REAR DOOR, CUT/WELD LH SIDE SILL PANEL, REPAIR LH FRONT DOOR, REPAIR LH REAR FENDER, REPAIR REAR BUMPER FACE	2 1/2 X 450			2700.00 1125
E PNT88000 TRANSFER LH REAR DOOR TRIM, DOOR GLASS, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL				120.00
E PNT88000 REMOVE AND INSTALL FLOOR CARPET AND SIDE TRIM CABIN TO FACILITATE REPAIR WORK	(photo)			120.00
E PNT98000 PAINT WORK SPRAY LH FRONT DOOR, LH REAR DOOR, LH SIDE SILL PANEL, LH REAR FENDER, REAR BUMPER AND AFFECTED PORTION	5 X 350			2100.00 1750
E PNT88000 REMOVE AND INSTALL AERO KIT				80.00
M SUNDRY APPLY BODY SEALANT				40 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
M SUNDRY PERFORM RUST PREVENTION				40 80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY LABOUR RENEW LH REAR SPORT RIM INCLUDING BALANCING				30.00
M SUNDRY RE-APPLY ZERTONA COATING	(provide sales agreement)			320.00
M SUNDRY SUNDRIES				20 50.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Abdul Jalil Bin Mohamad Reg No/Reg Date SFZ7767S / 12/02/201 Date In/Mileage / 0 Chassis No GF7W0401119 Engine No 4J11XK6012 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	08/02/2021/ 09:49	QUD	247 / DonBong	62784

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SIDE SILL,FR FLOOR,OTR LH X <del>EA</del> NM	1.00	802.00	23.00	617.54
M PANEL ASSY,RR DOOR,LH / DO	1.00	942 <del>937.00</del>	23.00	721.49
M W/STRIP,RR DOOR OPNG,FR LH / X NM	1.00	129.00	23.00	99.33
M W/STRIP,R/DR OPN,LWR OTR L / X NM	1.00	33.00	23.00	25.41
M TAPE,RR DOOR SASH / NPC	1.00	42.00	23.00	32.34
M TAPE,RR DOOR SASH / NPC	1.00	42.00	23.00	32.34
M GARNISH,FR DOOR,LH / CUT	1.00	190.00	23.00	146.30
M GARNISH,RR DOOR,LH / CUT	1.00	164.00	23.00	126.28
M AIR DAM,SIDE,LH X NM	1.00	541.00	23.00	416.57
M AERO KIT - OUTLANDER X CUT (Salvage from SLX 7631P)	1.00	1554.00	00.00	1554.00
M WHEEL,SPARE TIRE DISC / CUT	1.00	1102.00	23.00	848.54
M MOULDING,RR WHEEL ARCH,LH / CUT	1.00	199.00	23.00	153.23
M MOULDING,RR BUMPER,LH / CUT	1.00	106.00	23.00	81.62

Estimate

SURVEYOR NAME: Steve (CLKK) 8/2/21, 3:00pm  
 SURVEYOR SIGNATURE: OD-NM AL  
 DATE: Excess - ?  
 REMARKS: P/P  
 Ry Del  
 7 days

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display the relevant part(s) during resurvey  
 • This party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Authorized signatory and company stamp

Confirm & accepted by	7% GST on	Nett	
		10804.99	10,804.99
			756.35
	<b>Total Payable</b>		<b>11,561.34</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.