



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR GOH PUAY KEE	Cust No/Name KCV08899/Mr Goh Puay Kee
BLK 296D CHOA CHU KANG AVENUE 2	Reg No/Reg Date SMD570X / 31/07/201
#08-60	Date In/Mileage / 0
SINGAPORE 684296	Chassis No JMAXTGK1WJZ002793
Contact No	Engine No 4B40DR0518
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV08899	CRDVCH	08/02/2021/ 13:52	BLC	442 / CocoLu	62725			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2250.00
RENEW FRT ¹ BUMPER, FRT ¹ FENDER LH, REPAIR FRT WHEELHOSUING LH, FRT ¹ DOOR LH, BONNET					2 1/2 X 450			1125
E PNT98000								1750.00
SPRAY PAINT FOR FRT ¹ BUMPER, FRT ¹ FENDER LH, BONNET, FRT DOOR ¹ LH, FRT WHEEL HOUSING LH,					3 X 350			1050
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								30.00
A 54900099								450.00
CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 54900099								120.00
RENEW FRT UNDER CARRIAGE								460.00
M SUNDRY								20.00
TRANSFER FRT LEFT RIM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
SUPPLY FRT LEFT TYRE								
M SUNDRY								
Sundry								
M	FACE,FR BUMPER	/ DO			1.00	714.00	00.00	714.00
M	GARNISH,FR BUMPER SIDE	(change) - CUT			1.00	73.00	00.00	73.00
M	GARNISH,FR BUMPER SIDE	(change) - BR			1.00	214.00	00.00	214.00
M	EXTENSION,FR BUMPER	? X NM			1.00	317.00	00.00	317.00
M	COVER,FR BUMPER	? X NAI			1.00	380.00	00.00	380.00
M	BRACKET,FR BUMPER SIDE,LH	/ BR			1.00	18.00	00.00	18.00
M	REINFORCEMENT,FR BUMPER	X NM			1.00	552.00	00.00	552.00
M	REINFORCEMENT,FR BUMPER	X NAI			1.00	235.00	00.00	235.00
M	REINF,FR BUMPER SIDE,LH	? X NAI			1.00	35.00	00.00	35.00
M	BAR,FR BUMPER GUARD	X NAI			1.00	100.00	00.00	100.00
M	GRILLE ASSY,RADIATOR	? X NM			1.00	484.00	00.00	484.00
M	COVER,FR BUMPER GRILLE	X NM			1.00	302.00	00.00	302.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR GOH PUAY KEE	Cust No/Name KCV08899/Mr Goh Puay Kee
BLK 296D CHOA CHU KANG AVENUE 2	Reg No/Reg Date SMD570X / 31/07/201
#08-60	Date In/Mileage / 0
SINGAPORE 684296	Chassis No JMAXTGK1WJZ002793
Contact No	Engine No 4B40DR0518
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV08899	CRDVCH	08/02/2021/ 13:52	BLC	442 / CocoLu	62725			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	INSULATOR,FR FENDER,LH	/	TN		1.00	52.00	00.00	52.00
M	FENDER,FR LH	/	DD		1.00	599.00	00.00	599.00
M	SHIELD,FR WHEELHOUSE,LH	/	CRU		1.00	135.00	00.00	135.00
M	PAD,FR FENDER	X	NM		1.00	57.00	00.00	57.00
M	COVER,ENG ROOM UNDER,FR	?	X NM		1.00	158.00	00.00	158.00
M	MOULDING,FR WHEEL ARCH,LH	/	CUT		1.00	151.00	00.00	151.00
M	GARNISH,SIDE SILL,LH	X	NM		1.00	91.00	00.00	91.00
M	GARNISH,FR PILLAR,LH	?	X NM		1.00	123.00	00.00	123.00
M	MIRROR ASSY,DOOR,LH	X	NM		1.00	824.00	00.00	824.00
M	COVER,DOOR MIRROR,OTR LH	X	R		1.00	100.00	00.00	100.00
M	HEADLAMP ASSY,LH	/	OR		1.00	1976.00	00.00	1976.00
M	BRACKET,HEADLAMP	?	X NM		1.00	16.00	00.00	16.00
M	BRACKET,HEADLAMP	?	X NM		1.00	12.00	00.00	12.00
M	WHEEL,DISC	/	CUT		1.00	1102.00	00.00	1102.00
M	SHAFT AS,FR AXLE DRIVE,LH	?	X NM		1.00	1106.00	00.00	1106.00
M	ARM ASSY,FR SUSP,LWR LH	?	BT		1.00	323.00	00.00	323.00
M	CROSSMEMBER,FR AXLE,NO.1	?	X NM		1.00	1114.00	00.00	1114.00
M	HUB ASSY,FR WHEEL	?	X NM		1.00	383.00	00.00	383.00
M	KNUCKLE,LH	?	X NM		1.00	346.00	00.00	346.00
M	STRUT,FR SUSP,LH	/	BT		1.00	413.00	00.00	413.00
M	LINK,FR SUSP STABILIZER	/	BT		1.00	137.00	00.00	137.00
M	BAR,FR SUSP STABILIZER	X	NM		1.00	291.00	00.00	291.00
M	BEARING,FR SUSP STRUT	/	MC		1.00	32.00	00.00	32.00
M	INSULATOR,FR SUSP STRUT	/	BT		1.00	136.00	00.00	136.00
M	PAD,FR SUSP SPRING,LWR	?	X NM		1.00	15.00	00.00	15.00
M	GEAR & LINK ASSY,STEERING	?	X NM		1.00	1399.00	00.00	1399.00
M	END ASSY,TIE ROD	?	X NM		1.00	76.00	00.00	76.00
M	SENSOR,FR ABS,LH	X	NM		1.00	240.00	00.00	240.00
M	ACTUATOR,HEADLAMP WASHER,L	?	X NM		1.00	113.00	00.00	113.00

Estimate

Steve (LKK)
OD-NM AL
Excess - ?
8/2/21, 4:40pm
010

Estimate

Steve (CLKK)
 OD-NM AL
 Excess -?
 8/2/21, 4.00pm
 P/P

Ry Bol SPY
 6 days

Confirm & accepted by after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

Nett 20,174.00
 1412.18
 7% GST on 20174.00
 Total Payable 21,586.18

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.