

AIG

Vehicle number	SLF3903B
Make / Model	TOYOTA WISH
Chassis number	JTDGG20W30J004936
Accident date	6/2/21
Reference	2102-18

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER	765.50 <i>de</i>
2	REAR BUMPER RETAINER	151.20 <i>LH de - RH X</i>
2	REAR BUMPER BRACKET	120.30 <i>LH-? RH X</i>
2	REAR BUMPER REFLECTOR	173.60 <i>LH-? RH X</i>
1	END PANEL	803.87 <i>bt</i>
1	END PANEL TOP GARNISH	382.61 <i>de</i>
1	KEYLESS SENSOR	281.60 <i>?</i>
1	KEYLESS SENSOR HOLDER	102.20 <i>?</i>
1	TAILGATE	1370.62 <i>bt</i>
1	TAILGATE WEATHERSTRIP	229.10 <i>cut</i>
1	TAILGATE LOCK	509.20 <i>bt - photo.</i>
2	TAILGATE EMBLEM - VALVE MATIC	54.59 <i>we</i>
1	TAILGATE EMBLEM - LOGO	65.29 <i>we</i>
1	TAILGATE GLASS MOULDING	180.00 <i>we</i>
1	TAILGATE OUTER CHROME GARNISH	386.50 <i>x</i>
2	TAILGATE LAMP	854.56 <i>LH-? RH X</i>
1	TAILGATE INNER TRIM BOARD	331.90 <i>?</i>
1	FRONT BUMPER	565.80 <i>de - photo.</i>
2	FRONT BUMPER COVER	287.50 <i>x</i>
2	FRONT BUMPER RETAINER	138.00 <i>?</i>
1	FRONT BUMPER REINFORCEMENT	327.35 <i>?</i>
1	FRONT BUMPER SPONGE	115.00 <i>?</i>
1	FRONT BUMPER LOWER GRILLE	126.50 <i>x</i>
1	FRONT GRILLE	454.25 <i>?</i>
1	FRONT GRILLE EMBLEM	55.00 <i>x</i>
1	FRONT SUPPORT PANEL	1477.50 <i>Ry</i>
1	FRONT SUPPORT PANEL TOP GARNISH	292.10 <i>x</i>
1	BONNET	931.50 <i>bt</i>
1	BONNET LOCK	109.25 <i>?</i>
1	BONNET INSULATOR	454.24 <i>x</i>
2	BONNET HINGE	126.50 <i>Ry</i>
1	BONNET EMBLEM - LOGO	91.30 <i>wey</i>
1	AIRCON CONDENSER	1725.00 <i>x</i>
1	RADIATOR	2305.75 <i>x</i>
2	FRONT HEADLAMP	2185.00 <i>cray LH - photo</i>
		18530.18
Less 25%		4632.54
		13897.64

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	40.00 30.00 ✓
1 SET	FRONT GRILLE CLIP	30.00 20.00 ✓
1 SET	BONNET INSULATOR CLIP	20.00 X
1 BOT	COOLANT	60.00 X
1 SET	REAR BUMPER CLIP	40.00 30.00 ✓
1 SET	REAR NUMBER PLATE	80.00 60.00 ✓
1 SET	WINDSCREEN SEALANT	120.00 60.00 ✓
1 SET	REVERSE SENSOR	400.00 200.00 ✓
Subtotal		790.00
Balance C/F		14687.64
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30.00 ✓
2	REMOVE,RENEW CONDENSER AND TOP UP GAS	200.00 X
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 X
4	REMOVE, REFIT REAR WINDSCREEN	200.00 120.00 ✓
5	REMOVE, REFIT AND REPLACE REVERSE SENSOR	200.00 30.00 ✓
6	PANEL BEATING ON AFFECTED AREAS	1600.00 1000.00 ✓
7	SPRAY PAINTING ON AFFECTED AREAS	1600.00 1000.00 ✓
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40.00 ✓
Subtotal		4210.00
Grand total		18897.64

Tanpin 97495749
 'WP' 2/2/21 E Spr
 1/3 Resurvey after repair
 Tanpin e/Phantom
 8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: