

AIG

Vehicle number	SLF3903B
Make / Model	TOYOTA WISH
Chassis number	JTDGG20W30J004936
Accident date	6/2/21
Reference	2102-18

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	491.90 765.50 <i>de</i>
2	REAR BUMPER RETAINER	75.60 151.20 <i>LH de RH X nn</i>
2	REAR BUMPER BRACKET	60.15 120.30 <i>LH de RH X nn</i>
2	REAR BUMPER REFLECTOR	86.80 173.60 <i>LH de RH X nn</i>
1	END PANEL	645.10 803.87 <i>de</i>
1	END PANEL TOP GARNISH	218.97 382.61 <i>de</i>
1	KEYLESS SENSOR	189.50 281.60 <i>de</i>
1	KEYLESS SENSOR HOLDER	102.20 <i>de</i>
1	TAILGATE	1175 1370.62 <i>de</i>
1	TAILGATE WEATHERSTRIP	229.10 <i>cut</i>
1	TAILGATE LOCK	361.60 509.20 <i>de - photo</i>
2	TAILGATE EMBLEM - VALVE MATIC	54.59 <i>de</i>
1	TAILGATE EMBLEM - LOGO	65.29 <i>de</i>
1	TAILGATE GLASS MOULDING	180.00 <i>de</i>
1	TAILGATE OUTER CHROME GARNISH	386.50 <i>X nn</i>
2	TAILGATE LAMP	387.50 854.56 <i>LH de RH X nn</i>
1	TAILGATE INNER TRIM BOARD	299.70 331.90 <i>de</i>
1	FRONT BUMPER	565.80 <i>de - photo</i>
2	FRONT BUMPER COVER	287.50 <i>X nn</i>
2	FRONT BUMPER RETAINER	138.00 <i>X nn</i>
1	FRONT BUMPER REINFORCEMENT	327.35 <i>de</i>
1	FRONT BUMPER SPONGE	115.00 <i>de</i>
1	FRONT BUMPER LOWER GRILLE	126.50 <i>X nn</i>
1	FRONT GRILLE	286.20 454.25 <i>de</i>
1	FRONT GRILLE EMBLEM	55.00 <i>X nn</i>
1	FRONT SUPPORT PANEL	1477.50 <i>Ry</i>
1	FRONT SUPPORT PANEL TOP GARNISH	292.10 <i>X nn</i>
1	BONNET	787 931.50 <i>de</i>
1	BONNET LOCK	109.25 <i>X nn</i>
1	BONNET INSULATOR	454.24 <i>X nn</i>
2	BONNET HINGE	126.50 <i>Ry</i>
1	BONNET EMBLEM - LOGO	91.30 <i>de</i>
1	AIRCON CONDENSER	1725.00 <i>X nn</i>
1	RADIATOR	2305.75 <i>X nn</i>
2	FRONT HEADLAMP <i>each</i>	2185.00 <i>de</i> <i>LH - photo</i> 1900
Less 25%		18530.18
		4632.54
		13897.64

8695.65
 6521.74

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	40.00 30w
1 SET	FRONT GRILLE CLIP	30.00 20w
1 SET	BONNET INSULATOR CLIP	20.00 XAA
1 BOT	COOLANT	60.00 X un
1 SET	REAR BUMPER CLIP	40.00 30w
1 SET	REAR NUMBER PLATE	80.00 66- 45
1 SET	WINDSCREEN SEALANT	120.00 60w
1 SET	REVERSE SENSOR	400.00 200w
Subtotal		790.00
Balance C/F		14687.64
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30.
2	REMOVE, RENEW CONDENSER AND TOP UP GAS	200.00 X un
3	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	200.00 X un
4	REMOVE, REFIT REAR WINDSCREEN	200.00 120.
5	REMOVE, REFIT AND REPLACE REVERSE SENSOR	200.00 30.
6	PANEL BEATING ON AFFECTED AREAS	1600.00 1200
7	SPRAY PAINTING ON AFFECTED AREAS	1600.00 1200
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40.
Subtotal		4210.00
Grand total		18897.64

Tarphn 97795744
 'wp' 2/2/21 @ 5pm
 1/3 Resny after repair
 Tarphn @ 1/1/2020
 8 days

9526.74
 11587.600
 2620

REPAIR PERFORMA INVOICE

AIG

Vehicle number	SLF3903B
Make / Model	TOYOTA WISH
Chassis number	JTDGG20W30J004936
Accident date	6/2/21
Reference	2102-18

Supplementary

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	TAILLAMP LH	527.38
1	SPARE TYRE COMPARTMENT	1203.60
		1730.98
	Less 25%	432.74
		1298.24

321
 25% 240.75

9526.74
 240.75

 9767.49
 4/5 @ 7800
 * 8 days