

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

10-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1153 U

1 pc	Tailgate lower garnish	X Repair ✓ CRA	\$	362.61	✓
1 pc	Tailgate lock	X	\$	216.48	
1 pc	Tailgate striker	X	\$	36.50	
1 pc	Tailgate inner trim	X	\$	431.12	
1 pc	Tailgate weatherstrip	X	\$	276.98	
1 pc	Emblem I30	— me.	\$	27.80	✓
1 pc	Emblem CRDI	X NN	\$	29.40	✓
1 pc	Emblem Hyundai	X NN	\$	29.40	
1 pc	Rear bumper	— de	\$	811.11	✓
1 pc	Rear bumper sponge	⊗ NN	\$	79.20	
1 pc	Rear bumper reinforcement	⊗ NN	\$	815.64	
1 pc	Rear bumper reinforcement centre	⊗ NN	\$	79.20	
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X NN	\$	104.40	
2 pcs	Rear bumper n/s & o/s reflector @ \$107.50	⊗ NN	\$	215.00	
			\$	3,514.84	1230.92
Less 20%			\$	702.97	
			\$	2,811.87	984.73

S/NETT

1 set	Rear bumper clips	— me.	\$	48.00	✓
1 set	Reverse sensor	X NN	\$	280.00	
1 set	Tailgate stickers	— me.	\$	100.00	30
1 set	Tailgate lower garnish clips	— me.	\$	38.00	✓
1 pc	Rear bumper top protector	— de	\$	80.00	50

166

10-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1153 U

Sundry	\$	50.00	X NR
To dismantle and replace reverse sensor and test system	\$	80.00	40.
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X NR
To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel. Including to knock-out, straighten, repair, reshape of the tailgate, etc	\$	800.00	200
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, tailgate	\$	800.00	300
To apply rustproofing on the repaired and replaced panels	\$	80.00	X NR
Total	\$	<u>5,347.87</u>	<u>540</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

1690.73

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

-20%: 1350

2 Days -
Unpsum Repair
After repair photos.
Gmo Qiang - 82880282
Gmo Qiang @ lkkauto.com

22/2/2021

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--