

ASS. REC. BY:

REF:

CTZ/21001849/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD LTP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMPCSNW00061442000

Claims No. SNM21D200623/C01/THAMYL

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: B160k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Tan San

Veh No:

SKX 7050C Yr Regn: 12, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Porsche Cayman C.C. 3436

Colour

M. Black A/C: Insured / Std / NI / NA

Sp. Reading

95681 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WPOZ8898ZCS770373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/35ZR19

R: 285/35ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4 mm

R/Bal.

5 mm

L/Bal.

4 mm

L/Bal.

5 mm

D.O.A.

1/2/21

D.O.I.

9/2/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Unable to print estimate

When said price quoted is his cost, unable to adjust

23/4/21

Kenneth confirmed repair sum \$26,500 (Red 3400, 11%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S - RS. SI

F. M. S.

O. H. S.

TOTAL

2) 26/4/21 - Typist

415 - typist

Report Format: Merimen

Lump Sum / I.B.I: (\$ RS \$26,500

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

SPEED CLINIC

10 Ang mo kio industrial pk 2A
#02-07 Singapore 568047
Tel:81637753 fax : Sam chua

DATE:04/02/2021

Ref SKX7050C

To: Motor Claim Department
China Taiping Insurance

*Not Withheld
Repair Sum @ 26,500/- By exch*

Dear Sir

Vehicle Owner Khor Teck Lin would like to make claim under own damage .Insurance policy DMPCSNW00061442000

Detail of Work and parts estimate cost of repair SKX7050C

1. Front suspension \$3800 puncture
2. Left gen 2 black edition Xenon dynamic adaptive headlight with calibration work \$5000 broken
3. Front bumper \$4000 cracked
4. Front bonnet with lock ,seal,trims, stopper catch ,hinge ,damper \$4500 distorted
5. Left fender and bracket \$1600 bent
6. front cross penals support and penal welding work \$3000 -\$2000
7. spray paint n matt sticker wrap \$3000 -\$1200 (without Matt wrap)

Total estimate cost of repair sum to \$24900

Car is at our workshop 10 Ang Mo Kio park 2a #02-07 Singapore 568047 , please kindly arrange your surveyor to inspect this car at our premises .

please kindly look into it, Thank you

best regards

sam chua
81637753

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

SPEED CLINIC

10 Ang mo kio industrial pk 2A
#02-07 Singapore 568047
Tel:81637753 fax : Sam chua

DATE:22/02/2021

Ref:O/R: SNM21D200623/C01/SKX7050C/THAMYL / FW: SKX7050C own damage claim

To: Motor Claim Department
China Taiping Insurance

Dear Sir

Additional cost of repair item

Detail of Work and additional parts and cost of repair for SKX7050C

1. Aircon system \$2000 *Pd ✓*
2. Radiator ^{sys} system \$2000 *Hws cm ✓*
3. Front bumper support \$1000 *At ✓*
reinforcement

Total additional cost of repair sum to \$5000

Car is at our workshop 10 Ang Mo Kio park 2a #02-07 Singapore 568047 , please kindly arrange your surveyor to inspect this car at our premises .

please kindly look into it, Thank you

best regards

sam chua
81637753