



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAY HEAN CHEOW (ZHENG XIANZHAO) Reg No/Reg Date SMJ5395X / 11/03/201 Date In/Mileage / 0 Chassis No KNAF3416MK5027526 Engine No G4FGJH716076 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/02/2021/ 12:51	QUE	261 / Edwin Caina	28720			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2400.00
RENEW RR BUMPER , BOOTLID & RR END PNL					400 X 2			800
REPAIR / ALIGN RR FLR PNL , LHR FENDER & RHR FENDER								2100.00
E PNT98000								700
RESPRAY RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER & RHR FENDER					350 X 2			120.00
E PNT88000								120.00
REMOVE & REFIT BOOTLID COMPONENT								120.00
E PNT88000								30.00
REMOVE & REFIT RR FLR BOARD, TRIM, CARPET TO FACILITATE REPAIR					(pmb)			120.00
A 54900099								50.00
CHECK WIRING ELECTRICAL SYSTEM								60.00
A 10028901								220.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								80.00
USING HI-SCAN PRO TEST								40
M SUNDRY								40.00
SUPPLY RR NUMBER PLATE WITH CASING								20.00
E PNT88000								520.80
REMOVE & REFIT REVERSE SENSOR								192.80
M SUNDRY								15.20
SUPPLY REVERSE SENSOR								15.20
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
SUPPLY BODY PNL SEALANT								
M SUNDRY								
SUPPLY C&C BADGE								
M SUNDRY								
Sundries					1.00	651.00	20.00	520.80
M COVER-RR BUMPER					1.00	241.00	20.00	192.80
M COVER-RR BUMPER LWR					1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP, LH					1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP, RH					1.00	19.00	20.00	15.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /TAY HEAN CHEOW (ZHENG XIANZHAO) Reg No/Reg Date SMJ5395X / 11/03/201 Date In/Mileage / 0 Chassis No KNAF3416MK5027526 Engine No G4FGJH716076 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/02/2021/ 12:51	QUE	261 / Edwin Caina	28720			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M LAMP ASSY-SIDE T/SIGNAL, LH			X NN		1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH			X NN		1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS			X NN		1.00	207.00	20.00	165.60
M BEAM-RR BUMPER			GR		1.00	318.00	20.00	254.40
M STAY-RR BUMPER LH			BT		1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH			BT		1.00	65.00	20.00	52.00
M ANTENNA ASSY-SMARTKEY			X NN		1.00	46.00	20.00	36.80
M BRACKET-RR BEAM UPR MTG, LH			GR		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH			X NN		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR			GR		1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG			X NN		2.00	6.00	20.00	9.60
M COVER-RR BUMPER UNDER, RH			X NN		1.00	33.00	20.00	26.40
M BRACKET ASSY-RR BPR SIDE UPR, LH			X NN		1.00	25.00	20.00	20.00
M BRACKET ASSY-RR BPR SIDE UPR, RH			X NN		1.00	31.00	20.00	24.80
M COVER-RR BUMPER UNDER, LH			X NN		1.00	33.00	20.00	26.40
M TRIM ASSY-RR TRANSVERSE			X NN		1.00	41.00	20.00	32.80
M PANEL ASSY-BACK			DD		1.00	324.00	20.00	259.20
M PANEL ASSY-TRUNK LID			DD		1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID, LH			X NN		1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID, RH			X NN		1.00	97.00	20.00	77.60
M W/STRIP-TRUNK LID OPNG			CRU		1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID			CUT		1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID			X NN		1.00	40.00	20.00	32.00
M LOGO ASSY-KIA SUB			MC		1.00	32.00	20.00	25.60
M EMBLEM-CERATO			MC		1.00	28.00	20.00	22.40
M LAMP ASSY-CENTER GARNISH			X NN		1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE, LH			X NN		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE, RH			X NN		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, LH			X NN		1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE, RH			X NN		1.00	675.00	20.00	540.00

Steve (LKK)

Confirm & accepted by

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Authorized signatory and company stamp

Nett

11,480.00

7% GST on

11480.00

803.60

Total Payable

12,283.60

Express - ?

P/P, R/L spg, 7 days

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.