



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|-----------------------------|---------------------------|-------------------------------|
| CHEN THIM KWANG | Cust No/Name | /CHEN THIM KWANG |
| 14 ANG MO KIO CENTRAL 3 | Reg No/Reg Date | SM7211C / 15/07/202 |
| #12-23 | Date In/Mileage | / 0 |
| SINGAPORE 567747 | Chassis No | MMBSTA13AKH003375 |
| Contact No Mobile: 96731859 | Engine No | 3A92UJB1449 |
| | Make/Model | MIT/19MY ATTRAGE 1.2 CVT |
| | Colour/Trim | P57 WINE RED PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---|-------|-------------------|-----|--------------|--------|------------|-------|-----------|
| CSM00041 | Cash | 08/02/2021/ 12:34 | | 442 / CocoLu | 62792 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | 2250.00 |
| RENEW REAR BUMPER, BOOTLID, REAR LAMP HOUSING RH, REAR END PANEL | | | | | 5 | 450 | | |
| REAR AIRDAM, REPAIR REAR, FENDER LH, REAR COMPARTMENT, REAR FENDER RH | | | | | | | | 80 100.00 |
| E PNT88000 | | | | | | | | 60.00 |
| REMOVE & INSTALL REAR AIR DAM | | | | | | | | 300.00 |
| E PNT88000 | | | | | | | | 3150.00 |
| REMOVE & INSTALL PARKING SENSOR | | | | | | | | |
| E PNT88000 | | | | | | | | |
| REMOVE & INSTALL REAR COMARTMENT TRIMS | | | | | | | | |
| E PNT98000 | | | | | 6 | 350 | | |
| SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL, BOOTLID | | | | | | | | 30.00 |
| REAR COMPARTMENT, REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH | | | | | | | | 120.00 |
| A 54900099 | | | | | | | | 80.00 |
| CHECK WIRING & ELECTRICAL SYSTEM | | | | | | | | 40.00 |
| A 10028901 | | | | | | | | 220.00 |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST | | | | | | | | 20.00 |
| USING HI-SCAN PRO TEST | | | | | | | | |
| M SUNDRY | | | | | | | | |
| APPLY SEALANT FOR ACCIDENT PORTION | | | | | | | | |
| M SUNDRY | | | | | | | | |
| C&C LOGO | | | | | | | | |
| M SUNDRY | | | | | | | | |
| SUPPLY PARKING SENSOR | | | | | | | | |
| M SUNDRY | | | | | | | | |
| Sundry | | | | | | | | |
| M UNPAINTED BODYKITS | | | | | 1.00 | 1643.00 | 00.00 | 1643.00 |
| M FACE, RR BUMPER | | | | | 1.00 | 751 748.00 | 00.00 | 748.00 |
| M BRACKET, RR BUMPER, RH | | | | | 1.00 | 28.00 | 00.00 | 28.00 |
| M BRACKET, RR BUMPER, LH | | | | | 1.00 | 28.00 | 00.00 | 28.00 |
| M PANEL, RR COMB LAMP HSG, RH | | | | | 1.00 | 60.00 | 00.00 | 60.00 |
| M PANEL, RR COMB LAMP HSG, LH | | | | | 1.00 | 60.00 | 00.00 | 60.00 |
| M PANEL, RR END | | | | | 1.00 | 427 425.00 | 00.00 | 425.00 |
| M PANEL, TRUNK LID | | | | | 1.00 | 795 791.00 | 00.00 | 791.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|---|
| CHEN THIM KWANG 14 ANG MO KIO CENTRAL 3 #12-23 SINGAPORE 567747 Contact No Mobile: 96731859 | Cust No/Name /CHEN THIM KWANG Reg No/Reg Date SMT7211C / 15/07/202 Date In/Mileage / 0 Chassis No MMBSTA13AKH003375 Engine No 3A92UJB1449 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|---------------------------|-------------------|-----|--------------|--------|------------|-------|--------|
| CSM00041 | Cash | 08/02/2021/ 12:34 | | 442 / CocoLu | 62792 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | WEATHERSTRIP, TRUNK LID | X | NN | | 1.00 | 157.00 | 00.00 | 157.00 |
| M | HINGE, TRUNK LID, RH | X | NN | | 1.00 | 203.00 | 00.00 | 203.00 |
| M | HINGE, TRUNK LID, LH | X | NN | | 1.00 | 203.00 | 00.00 | 203.00 |
| M | LATCH, TRUNK LID | X | NN | | 1.00 | 218.00 | 00.00 | 218.00 |
| M | GARNISH, RR END PANEL | X | NN | | 1.00 | 336.00 | 00.00 | 336.00 |
| M | MARK, THREE-DIA | NP | | | 1.00 | 69.00 | 00.00 | 69.00 |
| M | MARK, ATTRAGE | NP | | | 1.00 | 21.00 | 00.00 | 21.00 |
| M | TRIM, RR END | CRU | | | 1.00 | 66.00 | 00.00 | 66.00 |
| M | BOARD, TRUNK ROOM FLOOR | BR | | | 1.00 | 195.00 | 00.00 | 195.00 |
| M | TRIM, TRUNK ROOM SIDE, RH | X | NN | | 1.00 | 160.00 | 00.00 | 160.00 |
| M | REFLECTOR | X | NN | | 1.00 | 23.00 | 00.00 | 23.00 |
| M | REFLECTOR | X | NN | | 1.00 | 23.00 | 00.00 | 23.00 |
| M | LAMP ASSY, COMB, RR RH | CRU | | | 1.00 | 335.00 | 00.00 | 335.00 |
| M | LAMP ASSY, LICENSE PLATE | X | NN | | 1.00 | 51.00 | 00.00 | 51.00 |

Estimate

Steve (LKK) 8/2/21, 3.00pm

DD-MM ALL

EXCESS - ?

P/P

M BL SK

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

Nett 12,213.00
 7% GST on 12213.00 854.91
Total Payable 13,067.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.