

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/DBE 21001860/hrs3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 3570X
at Workshop m/s RP.

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

948A

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Dep 15th
conv 12-2-11 LIA 836155

3rd 2yrs 6 mths. have good

24/2/11 4583200 confirmed n.e. Aln.

P/P \$950

Veh No:

SME 3570X

Yr Regn:

30/8/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mer Benz C180

c.c

1595

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

118845

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD2040312A 888587

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45-R17

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883 TEL:67452063

VEHICLE No: SME 3570X

1PC	FRONT BUMPER	2007 car/corn 1385.142	\$2,021.32	/	R
1PC	FRONT BUMPER PDC SENSOR N/S	11	\$225.00	X	
1PC	FRONT BUMPER SIDE RETAINER N/S	11	\$68.50	X	
1SET	FRONT BUMPER CLIPS	1 set	\$50.00	/	R
2PCS	FRONT BUMPER LOWER CHROME MOULDINGS @ \$118.00	1 set	\$236.00	/	R
1PC	HEADLAMP N/S	one 1622.30	\$2,850.00	/	R
1PC	FRONT FENDER N/S	R	\$912.30	X	
1PC	FRONT FENDER LOWER CHROME MOULDING N/S	all	\$102.00	/	R
1PC	FRONT SPORT RIM N/S	R	\$1,450.00	X	
		(102)	\$7,915.12		

TO CHECK WIRING
TO DISMANTLE & REFIX FRONT PDC SENSOR
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 50
11 \$50.00 X
\$120.00 80
\$580.00 300
\$680.00 500
TOTAL \$9,475.12

Not Authorized
2 hrs
~~2/5 @ 3200~~ 2 hrs
8/11/21
Whyche Attorney
LKK; Justin

P/P \$950

3395.62
10%
3056.05
4006.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: