

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/DBE 21001860/hrs3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / (P) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 3570X

at Workshop m/s

RP.

of

Insured:

SCG 282

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 50k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

948A

Vehicle: IN / OUT

Date:

Person Contacted:

Dep/Sec

Date / Time

Action / Instruction

conv 12-2-11 LIA 836155

3rd 2yrs 6 mths. have good

24/2/11 2/5 @ 3200 confirmed w.e. after.

Veh No:

SME 3570X

Yr Regn:

30/8/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

Mer Benz C180

c.c

1595

Colour

Black

A/C:

Insured / Std / NI / NA

Sp.Reading

118845

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD2040312A 888587

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

6/2/11

D.O.I.

8/2/11

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RP.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883 TEL:67452063

VEHICLE No: SME 3570X

1PC	FRONT BUMPER	Deep cut/Toen 1385.42	\$2,021.32	/
1PC	FRONT BUMPER PDC SENSOR N/S	11	\$225.00	X
1PC	FRONT BUMPER SIDE RETAINER N/S	11	\$68.50	X
1SET	FRONT BUMPER CLIPS	nee	\$50.00	/
2PCS	FRONT BUMPER LOWER CHROME MOULDINGS @ \$118.00	nee	\$236.00	/
1PC	HEADLAMP N/S	one 1022.20	\$2,850.00	/
1PC	FRONT FENDER N/S	R	\$912.30	X
1PC	FRONT FENDER LOWER CHROME MOULDING N/S	nee	\$102.00	/
1PC	FRONT SPORT RIM N/S	R	\$1,450.00	X
			\$7,915.12	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX FRONT PDC SENSOR	\$80.00	50
TO SPRAY RUST PROOFING	\$50.00	X
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$580.00	300
TO PUTTY & SPRAY PAINTING	\$680.00	500
TOTAL	\$9,475.12	

Not Authorized
2 hrs
2/5 @ 3200 2 hrs
8/11/21
Whyche Attorney
LKK; Justin

3395.62
10%
3056.05
4006.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: