

ASS. REC. BY:

REF:

MSG/21001862/KgF3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No: SJJ 5806M

at Workshop m/s

of

Insured:

SLN 8801L

Policy No.

30001622415

Claims No.

253115


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJJ 5806M

Yr Regn:

09, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. C. 180k

c.c

1597

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

237577

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2040462A 174703

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

4/12/21

D.O.I.

22/2/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/3 11/3/21 Typist 81950k Center

(RED \$10,813.50, 85%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 11/3/21 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format: TP

Lump Sum / L.B. (\$) 1,950

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SLN8801L

OUR REF.: SJJ5806M


TO: MSIG INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SJJ5806M

*Not Authorized
L1 Sy & 1950/h
Heavy After Paint
2 days*



DATE: 18/2/2021
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: MERCEDES BENZ C180K
CHASSIS NO.: WDD2040462A174703
ENGINE NO.: 27195231087651
YEAR MADE: 2008
ACCIDENT DATE: 4 February 2021

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BOOTLID		1	\$ R X 1,900.00
2	BOOTLID WEATHERSTRIP		1	\$ R X 200.00
3	BOOTLID HINGE LH		1	\$ R X 650.00
4	BOOTLID HINGE RH		1	\$ R X 650.00
5	BOOTLID LOCK		1	\$ R X 350.00
6	BOOT LID MERCEDES LOGO		1	\$ R X 55.00
7	TAIL LAMP LH		1	\$ R X 600.00 X
8	TAIL LAMP RH		1	\$ R X 600.00
9	REAR BUMPER 1345		1	\$ R X 1,600.00
10	REAR BUMPER RETAINER LH		1	\$ R X 75.00
11	REAR BUMPER RETAINER LH		1	\$ R X 75.00
12	REAR BUMPER REINFORCEMENT		1	\$ R X 750.00 X
13	REAR BUMPER SENSOR		41	\$ R X 1,000.00
14	REAR BUMPER CLIP		10	\$ R X 90.00 60
15	REAR BUMPER CHROME STRIP CENTER		1	\$ R X 120.00
16	REAR BUMPER CHROME STRIP LH 115		1	\$ R X 120.00
17	REAR BUMPER CHROME STRIP RH 115		1	\$ R X 120.00
18	REAR BUMPER TOWING COVER		1	\$ R X 60.00
19	EXHAUST PIPE TIP		2	\$ R X 450.00

TOTAL: \$ 9,465.00
LESS 10%: \$ (946.50)
PARTS TOTAL: \$ 8,518.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

SPECIAL NETT

REAR NUMBER PLATE & HOLDER
BODY SEALANT

1	\$	Sn X	50.00
1	\$	Sn X	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS

\$	250h	1,600.00
----	------	----------

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$	15h	150.00
----	-----	--------

TO REMOVE & REFIT ALL SENSOR

\$	60h	100.00
----	-----	--------

TO REALIGN EXHAUST PIPE

\$	nn X	80.00
----	------	-------

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$	nn X	100.00
----	------	--------

TO APPLY ANTI RUST COATING

\$	nn X	80.00
----	------	-------

TO SPRAY PAINT ON THE AFFECTED AREAS

\$	250h	1,200.00
----	------	----------

TOTAL:	\$	11,928.50
--------	----	-----------

7% GST:	\$	835.00
---------	----	--------

GRAND TOTAL:	\$	12,763.50
--------------	----	-----------