

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

JDD 72

at Workshop m/s

Enfir

of

Insured:

SLP 9162E

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

RM 5800

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

CMY 12-2-21

19/7/21 4/5 @ 1800 confirmed with MR Leo

Veh No:

JDD 72

Yr Regn:

119

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha 135LC

c.c

134

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

Bobby flap

C/No:

PMYUG0810K0107818

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

80 190-17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

2/2/21

D.O.I.

2/2/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &amp; N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) )

TOTAL

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Name : Nor Anash Afizi Bin Azman

Accident Date : 02-Feb-21

Vehicle No : JDD72

Vehicle Model : Yamaha 135LC

## Estimated Repair Costs

| Qty | Description<br>List Items |     | Amount S(\$)  |
|-----|---------------------------|-----|---------------|
| 2   | Front fork tube assy      | 295 | \$ 640.00 1pc |
| 1   | Front wheel rim           | 305 | \$ 380.00 ✓   |
| 1   | Fork under bracket        | 160 | \$ 185.00 ✓   |
| 1   | Front rim shaft           | 35  | \$ 45.00 ✓    |
| 1   | Front rim bearing         |     | \$ 38.00 ✓    |
| 1   | Front brake disc          | 145 | \$ 165.00 ✓   |
| 1   | Handle bar                |     | \$ 88.00 ✓    |
| 2   | Handle bar ends           | 35  | \$ 78.00 1pc  |
| 1   | Hand grip (1 set)         |     | \$ 55.00 X    |
| 2   | Side mirrors              |     | \$ 110.00 X   |
| 1   | Brake lever               |     | \$ 32.00 X    |
| 1   | Fairing assy (1 set)      | 465 | \$ 525.00 ✓   |
| 1   | Front footrest bracket    |     | \$ 65.00 ✓    |
| 2   | Front footrest rubbers    | 30  | \$ 70.00 1pc  |
| 1   | Gear pedal                |     | \$ 42.00 ✓    |
| 2   | Rear footrests            |     | \$ 80.00 X    |
| 2   | Rear footrest brackets    |     | \$ 156.00 X   |
| 1   | Rear fender               | 140 | \$ 180.00 ✓   |
| 2   | Rear signals              | 68  | \$ 140.00 1pc |
| 1   | Side stand                |     | \$ 70.00 X    |
| 1   | Main stand                |     | \$ 95.00 X    |
|     | taillamp                  |     | \$ 3,239.00   |
|     | headlamp                  |     | \$ 323.90     |
|     |                           |     | \$ 2,915.10   |

Less 10%

taillamp ~~✓~~ NPA  
headlamp ~~✓~~ NPA

Not Authorized

8/1/21  
1/3 #1800  
Hdy S.  
Zhephs After Repair

1911  
182  
1719.9

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Nor Anash Afizi Bin Azman

Accident Date : 02-Feb-21

Vehicle No : JDD72

Vehicle Model : Yamaha 135LC

## Estimated Repair Costs

### Special Net Items

|   |                                       |              |           |               |
|---|---------------------------------------|--------------|-----------|---------------|
| 1 | Number plate (1 set) <i>Rear Self</i> | \$           | 28.00     | <i>10</i>     |
| 2 | Fork oils <i>nlsn</i>                 | <i>15</i> \$ | 30.00     | <i>side</i>   |
| 2 | Fork oil seals <i>nlsn</i>            | <i>28</i> \$ | 56.00     | <i>1pc</i>    |
| 1 | Steering cone (1 set) <i>n</i>        | <i>50</i> \$ | 90.00     | <i>7</i>      |
| 1 | Rear box <i>Cur</i>                   | \$           | 280.00    | <i>180</i>    |
| 1 | Rear box bracket <i>17</i>            | \$           | 150.00    | <i>y</i>      |
|   |                                       |              | <u>\$</u> | <u>634.00</u> |

### S/No. Labour

|   |                                             |                       |                         |
|---|---------------------------------------------|-----------------------|-------------------------|
| 1 | To provide towing service                   | <i>11</i> \$ <i>X</i> | 50.00                   |
| 2 | To check wiring and reset headlamp focusing | \$ <i>117</i>         | 80.00                   |
| 3 | To provide labour                           | \$ <i>250</i>         | 420.00                  |
| 4 | To repair body frame                        | \$ <i>11</i>          | 380.00 <i>X</i>         |
|   |                                             |                       | <u>\$</u> <u>930.00</u> |

Grand Total

\$ 4,479.10

Singapore Dollars: Four Thousand Four Hundred Seventy-Nine and Cents: Ten only

*2257.90*

  
EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: