



iii Delete



Junk

**Block** 

## aigencrypt PRE-REPAIR INSPECTION REQUEST - SMM5830R vs SMU2962X (OI) on D.O.A.: 07/02/2021

(i) You replied on Mon 8/2/2021 4:55 PM

Subramaniam, Divyashni < Divyashni. Subramaniam SD @aig.com>









Mon 8/2/2021 4:42 PM

To: Admin A; assignments

Cc: Lim, Kok-Chong < Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa < NoorMariesa.AbuKassi

aigencrypt PRE-REPAIR INSPE... 235 KB

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested

(Please be informed that OI GIA Report is not available as insured has yet to report the accident)

Thanks & Regards,

## **Divyashni Subramaniam**

## **AIG**

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Janice Kee <janice.kee@ksteoptr.com> Sent: Monday, February 8, 2021 4:26 PM

To: Subramaniam, Divyashni < Divyashni.Subramaniam@aig.com >

Cc: Lim, Kok-Chong < Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa

<NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Teo, Ericweihong

<Ericweihong.Teo@aig.com>; Anthony Cheong <cheonganthony@yahoo.com.sg>

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE

SMU2962X AND SMM5830R ON 07/02/2021

This message is from an external sender; be cautious with links and attachments.