

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL: 6452 8211 FAX: 6451 7420

admin@supreme.sg

ESTIMATE

LINCOLN WONG ZI LIANG

c/o 46 Lenton Plain

Singapore 786548

Date: 19/2/2021

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: BMW 328 i / SKE 6843 M	
1 pc	rear bumper	R 1,265.70 X
1 pc	rear bumper side retainer	L 76.00 X
1 pc	rear lower arm	D 216.80 2
1 pc	rear trailing arm	M 256.20 2
1 set	bilstein b12 shock absorber (modified) 18005N	R 2,250.00 2
1 pc	rear knuckle arm	R 498.50 2
1 pc	wheel hub with bearing	M 521.80 2
1 pc	rear anti roll bar	L 386.30 X
1 pc	rear anti roll bar linkage	L 123.80 X
1 pc	alloy rim	M 985.70 1
1 pc	output shaft	R 2,380.90 X
	100 Sub-total	8,961.70
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.	200 600.00
	To spray painting on affected areas.	680.00 400
	To remove and replace rear undercarriage parts.	360.00 200
	4 Wheel computerised alignment.	85.00 60
	To replace alloy rim and balance wheel.	50.00 20
	Total	10,736.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Not Authorised
61 hrs @ 3900h
Painting After Paint
4 days